

RMD Path Ramali Mahasane Asthan to Ramali
Schedule XLV-Form No. 134
Uhas tola

Ajitesh Kumar Singh MMSY (SC)

Measurement FINAL DIVISION

Abstract

SUB-DIVISION

MEASUREMENT BOOK

9947161 . 3086

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
	1 st Year Maintenance Bill				
N/W:- R.W.D. Path Randuli Mahazeni Arthan to Randuli Har Tola.					
Agency:-	Ajit Singh Kumar				
Agri. No:-	S.B.D.	08/20-21			
Maintenance Period:-	27.02.24 to 26.02.25				
	Measurement				
① Restoration of Rain cuts.					
	8x3.70x	0.90x	0.30	=7.99	m ³
	6x4.90x	0.80x	0.30	=7.06	"
	10x4.60x	0.90x	0.30	=12.42	"
	10x4.25x	0.70x	0.30	=8.93	"
				= 36.40	m ³
② Making up Barms/Shoulders					
	12x5.30x	0.80		=50.88	m ²
	16x4.70x	0.90		=67.68	"
	8x4.20x	1.0		=33.60	"
	14x4.0	x0.90		=50.40	"
				= 202.50	m ²
③ Patch Repair over pot holes					
	6x2.50x	1.80		=27.0	m ²
	8x1.90x	1.0		=15.19	"
				= 42.19	m ²
④ Maintenance of B.T. Surface Road.					
	10x2.20x	1.40		=30.80	m ²
	10x1.10x	1.0		=11.0	"
				= 41.80	m ²
⑤ Maintenance of already planted trees					
	Continuation				
	= 66.00				

Scanned with CamScanner