

5th Year Maintenance Bill

71

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work - Meeting					
Bazaar San Chalm to Malhabad.					
Name of Agency - Sri					
Mirtumjay Kumar.					
Agg. No - SBD/16/2019-20					
Date of Completion - 23/6/20					
Date of Entry -					

<u>1/15.1</u> Restoration of Raincut					
Beams with Soil Mixture					
-- do -- all.					
8	6.50m	1.80m	0.30	=	28.08m ³
6	5.60m	1.90m	0.30	=	19.152m ³
10	7.40m	1.60	0.30	=	35.52
				Sum =	378.2
Total Qty.				=	82.752m ³

<u>2/15.2</u> Making of Beams					
Shoulder -- do -- all.					
12	4.5m	1.5m		=	81.0m ²
18	7.6m	1.2m		=	164.16m ²
8	5.6m	1.5m		=	67.2m ²
15	7.4m	1.4m		=	155.4m ²
Total Qty.				=	467.76m ²

<u>3/15.3</u> Repair of Pot holes					
filled -- do -- all.					
9	1.5m	1.2m	0.075	=	1.215m ³

