

Betaha to Rupaya folder.

Schedule XLV-Form No. 134

M.M.G.S.Y

Sitamarhi (S.C) DIVISION

Pamiha V

SUB-DIVISION

Area Construction

MEASUREMENT BOOK

3276

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
	2nd	Year	Main tenance Bill		
N/W! - Be toha to R4					paya Talca.
Agf. No! - 91-S.		B.P.f		20-21	
Agency! - Mohammmad Raza					
Main tenance period! - 20-05-23				to 19-05-24	
	Measurement				
1) Restoration of Rain cut.					
	14	4.70	0.90	0.30	= 17.77 M ³
	18	5.90	0.80	0.30	= 25.49 "
	20	3.50	0.90	0.30	= 18.90 "
					= 62.16 M ³
2) Making up Borms/Shoulder -					
	18	5.80	1.0		= 104.40 M ²
	22	5.40	0.90		= 106.92 "
	24	5.25	0.80		= 100.80 "
					= 312.12 M ²
3) Main tenance of MSS Road					
	12	2.07	1.80		= 43.20 M ²
4) Maintenance of H.P. culvert					
					= 3.0 No.
5) cutting of branches of trees shrub					
					= 2.0 NO
6) cutting of shrub from Road way					
					= 10.0 N ^o
7) White wash of C.D. Perimeter wall					
					= 63.0 M ²

[illegible]