

Betaha to Rupaya folder.

Schedule XLV-Form No. 134

M.M.G.S.Y

Sitamarhi (S.C) DIVISION

Pamiha V

SUB-DIVISION

Area Construction

MEASUREMENT BOOK

3276

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
<u>3rd Year Maintenance Bill</u>					
⑦ N/W. - Betahata Rupayya Tola.					
Ag. No. - 91- S.B.D. / 20-21					
Agency - Mohammad Raja.					
Maintenance Period - 20.05.24 to 19.05.25					
<u>Measurement</u>					
① Restoration of Rain cwt					
$18 \times 6.90 \times 0.90 \times 0.30 = 33.53 \text{ m}^3$					
$22 \times 5.40 \times 0.80 \times 0.30 = 28.51 "$					
$16 \times 2.75 \times 0.80 \times 0.30 = 10.56 "$					
$= 72.60 \text{ m}^3$					
② making up berm shoulder					

$26 \times 6.10 \times 1.0 = 158.60 \text{ m}^2$	
$18 \times 4.90 \times 0.80 = 70.56 "$	
$32 \times 4.65 \times 0.90 = 133.92 "$	
$= 363.08 \text{ m}^2$	
③ Patch Repair by M.S.	
$12 \times 2.40 \times 1.20 = 34.56 \text{ m}^2$	
$18 \times 1.70 \times 1.0 = 30.60 "$	
$= 65.04 \text{ m}^2$	
④ Repair to Potholes.	
$22 \times 1.80 \times 1.20 = 47.52 \text{ m}^2$	
$16 \times 1.05 \times 1.0 = 16.80 "$	
$= 64.32 \text{ m}^2$	
⑤ Maintenance of Silt culvert	
$= 3.0 \text{ m}^3$	

Continuation