

msy (sc)

W. H. C.
W. H. C.
S. Bhawan Se Karjige (Kothi) Mageran Tale
W. H. C. - G. S. S. S.

Schedule XLV-Form No. 134

28937 - Dr. H. Z. Ogilvie / Khandag, Khandag, Chappay

DIVISION

$\pi \in R \cdot u \cdot \rho(u)$ **SUB-DIVISION**
Chapra

Measurement Book

2011-5-28

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
<u>4th year maintenance work</u>					
Name of work:- Contn. and maint. of road from S. Bhawan Se Haridwar (North) Musakani to 19. via Gosalga d = 1.150 Km. under masonry (S).					
Agg. No. 04/SBD/ 2019- 2020.					
Name of Agency:- Bhood 1st. Sph. At:- Kairi, Riwilga, Dist Chapra.					
Agg. value Rs. (28,10,66) Lacs.					
Date of Commencement. 05-08-2019.					
Date of Completion 04-05-2020.					

Actual date of completion 04-05-20.

① Restoration of pavement / Besoms with Soil masonry.

$$7 \times 15 \times 0.75 \times 0.3 = 23.625 \text{ m}^3$$

$$4 \times 8 \times 0.75 \times 0.3 = 7.104 \text{ m}^3$$

$$5 \times 11 \times 0.75 \times 0.3 = 12.375 \text{ m}^3$$

$$6 \times 14 \times 0.75 \times 0.3 = 18.9 \text{ m}^3$$

$$3 \times 8 \times 0.75 \times 0.3 = 5.4 \text{ m}^3$$

$$7 \times 15 \times 0.75 \times 0.3 = 23.625 \text{ m}^3$$

$$91.029 \text{ m}^3$$

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(5) patch repairs over Bituminous Surface with 20mm. process Surfacing material do... do... do all comp. etc.					
16.5.24 A.C.	2x 6.45x0.7 =		13.545m ² .		
	4x 5.2x1.2 =		24.96m ² .		
	3x 5.3x0.7 =		11.13m ²		
	4x 7.3x0.8 =		23.36m ² .		
	3x 5.1x0.7 =		10.71m ²		
			83.705m ² .		
(6) Maintenance of c/p works					
					= 7 Nos.
(7) Road Sign :					
					0.17m ²

(8) White creosote of parapet walls of c/p works.					
					117.0 m ²
(9) Maintenance of 20mm.					
					2 Nos.

ABSTRACT OF COST

(1), Restoration of pavement/Bases with 80mm. concrete.

91.028m³ qty. vide T.M.B page (8)

@ 378.12/m³

Rs. 34,419.00

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
			Bot Rs 3		4,419=
(2) Making up Berms / Shoulders					
Stopping Excess Soil do. do. etc					
all Comp. job.					
105.00 sq. vide T.H.B page (69)					
@ Rs 57.14/m ²					
				Rs	23,141=
(3/3) Repair of pot holes filled with 4 (mm) W.B.M.					
83.705 m ² sq. vide T.H.B page (69)					
@ Rs 351.61/m ²					
				Rs.	29431=
4/4. patch repairs over pot holes					
83.705 m ² sq. vide T.H.B page (69)					
@ Rs 305.02/m ²					
				Rs	25,537=
5/5. patch repairs over Bituminous surface					
83.705 m ² sq. vide T.H.B page (69)					
@ Rs 322.43/m ²					
				Rs.	26,988=
6/6. Marle square of c/d curbs.					
71.08 sq. vide T.H.B page (70)					
@ Rs 1109.67/sq					
				Rs	7768=
7/7. Road Sign.					
0.14 m ² sq. vide T.H.B page (70)					
@ Rs 1066.5 /Km					
				Rs	181=00
				Rs.	1,47,460

Continuation

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
				Do. 1 B 1, 47, 460:	
8/12. white washing of parapet wall.					
117.0 on 2 fly. vide T.M.B page (70)					
@ 16. 54/m 2					
				B	1935=
9/9. H.A. of road 580 ft.					
0.51 km. fly. vide T.M.B page (70)					
@ 6 41.52/km.					
				fs	333200
				fs	149,728:
less 10 ft. below wall				fs	149722=
				fs	1,34,756=

Partial

16/5/2024

S.C. - Sd/-

Partial

16/5/2024

A2 Sd/-

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
5th Year maintenance work					
Name of work: - S. Bhawan					
Se Kaminga (Kothi) on Shari					
Tak via Gosola. Length = 1.25 km					
under ramossy (S.S.).					
Agreement No - 04/380/15-20					
Agree ment Amount of					
maintenance = 61000, 124200					
Date of Commencement:-					
05/08/2019					
Actual Date of comp:-					
04/05/2020.					
Name of Agency -					
Sri. Binod K. Singh, At					
Khairwar, Kheragans,					
Dist - Saran (Chapra)					
Detail of measurement					
1/15.2 Restoration of Raincuts /					
Being with soil mounum					
Continuation of completion.					

Abstract of cost

86

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
1/15.1 Restoration of Faircut/Bench					
vide item no - 1					103.26 m ²
Page no - 77					
@ 45348.32/m ² = 4539254.200					
2/15.2 making up of Bench/shoulder					
vide item no - 2					455.63 m ²
Page no - 78					
@ 4557.14/m ² = 4526039.200					
3/Repair of pot hole filled with					
vide item no - 3					105.47 m ²
Page no - 75					
105.47 m ² @ 4351.61/m ² = 4534084.00					
4/15.3(ii) Patch Repair on pot					
vide item no - 4					105.47 m ²
Page no - 80					
@ 45305.02/m ² = 4532270.00					
5/15.3(iii) Patch Repair on embankment					
vide item no - 5					105.47 m ²
Page no - 81					
@ 4322.43/m ² = 4534002.00					
451,68,550.200					

Continuation

(H)

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
6/15.9 maintenance of crop works					
side from north					
Page no - 82					6.170
@ 451109.67 / each					456658 = 00
7/15.9 maintenance of crop work					4000 3/25
side from north					
Page no - 82					
@ 451066.50 / km					2181 = 00
8/15.11					
maintenance of 200m x 15m					
side from north					
Page no - 82					
@ 45644.42 / km					245180 = 00
9/15.12					
cutting of shrubs from road					
side from north					
Page no - 82					5.000 / up
@ 45644.42 / each					4558 = 00
10/15.12					
cutting of branches at trees					
side from north					
Page no - 82					2.000 / up
@ 45105.39 / each					4521078
Continuation					212 = 00
					45175, 838 = 00

Continuation