

5th Year Maintenance Bill

X 64

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	

N/W:- Mauna Bishunpur Mangel
Sthar road to Mauna
Bishunpur Hrijan dola.

Agency:- Sanjeev Kumar

Agg No:- 12/SB01/2019-20

A Doc:- 15/10/2020

Detail measurement

① Restoration of rain Cuts

— do —

$$\begin{aligned} 6 \times 0.90 \times 0.30 &= 1.62 \text{ m}^3 \\ 8 \times 0.80 \times 0.30 &= 1.92 \end{aligned}$$

$$10 \times 0.75 \times 0.30 = 2.25 \text{ m}^3$$

$$7 \times 0.85 \times 0.40 = 2.38 \text{ m}^3$$

$$10 \times 0.65 \times 0.30 = 1.95$$

$$8 \times 0.80 \times 0.75 = 4.80$$

$$11 \times 1.0 \times 0.60 = 6.60$$

$$13 \times 0.90 \times 0.60 = 7.02$$

$$10 \times 1.30 \times 0.75 = 9.75$$

$$9 \times 0.90 \times 0.60 = 4.86$$

$$7 \times 0.85 \times 0.65 = 3.86$$

$$13 \times 0.90 \times 0.65 = 7.61$$

$$\text{Total} = 58.32 \text{ m}^3$$

② Marking of Beam/Shot

— do —



~~As~~
~~12/11/2025~~

Suman
1241-25
M

①	Soil	—	58.32 m ^d
②	Stone metal	—	7.90 m ^d
③	Bitumen	—	0.145 m ^r
④	Emulsion	—	0.08 m ^r

[Signature]