

3rd year maintenance.

51

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
N/Work:- main m ^o b road					
- from Pmasy road					
to madhopur Sahni tolg.					
N/Agency:- Vikash Kumar Singh.					
Agg. No:- 287/SBD/2020-21					
D.O.S:- 08.09.2020					
A.D.O.C:- 06.09.2021					
Date of measurement					
(1/1) Restoration of rain					
cuts do do - E/J					
9x 7.00x 0.70x 0.30 =					13.23m ³
8x 9.00x 0.90x 0.30 =					19.44m ³
7x 8.00x 0.80x 0.30 =					13.44m ³
9x 7.00x 0.90x 0.30 =					17.01m ³
8x 9.00x 0.80x 0.30 =					17.28m ³
7x 8.00x 0.90x 0.30 =					15.12m ³
8x 9.00x 0.80x 0.30 =					17.28m ³
8x 8.00x 0.90x 0.30 =					17.28m ³
				Qty =	130.08m ³
(3/2) main m ^o b earthen					
Shoulder do do - E/J					
9x 11.00x 0.90 =					89.10m ²
11x 12.00x 0.80 =					105.60m ²
12x 13.00x 0.80 =					124.80m ²
Continuation					Qty = 319.50m ²

