

2nd Year Maintenance

9

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work- Maintenance of road for					
Nimna Mukhiq Talq to Chandan					
(Babu Talq) under mussy					
Agency- Parmar Enterprises					
Agreement No- 186 SBD/2021-22					
Actual date of completion- 02/07/2023					
2nd year Maintenance? 03/07/2024					
Period } to 02/07/2025					

① Restoration of Kaimuth

1 X	6.10	X 1.20	X 0.30	=	2.20m ²
2 X	8.10	X 1.25	X 0.25	=	5.10m ²
2 X	7.10	X 1.15	X 0.25	=	4.02m ²
2 X	10.10	X 1.25	X 0.30	=	7.50m ²
2 X	11.10	X 1.28	X 0.30	=	8.45m ²
2 X	9.50	X 1.28	X 0.30	=	7.30m ²
2 X	7.50	X 1.20	X 0.30	=	5.40m ²
2 X	8.50	X 1.25	X 0.30	=	6.37m ²
3 X	10.50	X 1.25	X 0.30	=	11.81m ²
2 X	8.10	X 1.25	X 0.30	=	6.07m ²
2 X	9.20	X 1.10	X 0.25	=	5.06m ²
3 X	7.50	X 1.25	X 0.25	=	7.03m ²
3 X	10.10	X 1.25	X 0.30	=	11.25m ²
4 X	12.10	X 1.20	X 0.25	=	14.90
5 X	15.10	X 1.25	X 0.30	=	28.12
5 X	10.20	X 1.20	X 0.25	=	15.30

Continuation

145.21

Particulars	Details of actual measurement				Content of area
	No.	L.	B.	D.	
c. $h. 2.37/n^2$					R. 63 2820
(9) Maintenance of Trees by the road side					
Q-VTMS/12(9) = 240 Nos					
c. $h. 699 = 15/each$					R. 167 796
(10) Maintenance of road-sign					
Q-VTMS/12(8) = 1.50 Km					
c. $h. 1117 = 64/km$					R. 167 620
(11) Maintenance of zoom stones					
Q-VTMS/12(9) = 3 Km					
c. $h. 723.23/km$					R. 220020
					R. 339 40920
Add 12.5 f. GST (+)					40 52920
Add 1.5 f. L. cess (+)					339420
Add serg. bees (+)					125020
					R. 384 78220
Less 0.09 f. below (-)					34620
					R. 384 43620

R. 384 43620
04/08/25
J.E.

From 408.4
mE