

3rd year maintenance

59

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work - Maint. of road from					
Motiburg D pich to Kurmi					
Tola.					
Agency - Md. Anullah.					
Agg. No - 103 SBD / mmasy / 2021-22.					
Date of Start - 14 / 07 / 2021.					
Actual completion date - 13/07/2022 26/02/2022.					
Record Entry					
1.	Restoration of rain-				
	cuts do —				
	7X	4.23X	1.08X	0.30=	9.59m ³
	12X	6.41X	1.12X	0.30=	25.85m ³
	9X	5.37X	1.05X	0.30=	15.22m ³
	6X	3.75X	0.98X	0.30=	6.62m ³
	11X	7.59X	1.18X	0.30=	29.56m ²
	8X	4.34X	1.03X	0.30=	10.73m ²
					97.57m ² .
2.	Making of earthen				
	Shoulder do —				
	2X	6X	4.89X	1.56=	91.54m ²
	2X	5X	7.92X	1.44=	114.05m ²
	2X	11X	6.28X	1.39=	192.04m ²
	2X	9X	5.87X	1.60=	169.06m ²
	2X	7X	9.45X	1.67=	220.94m ²
	2X	8X	7.66X	1.58=	193.64m ²
	2X	12X	4.57X	1.33=	145.87m ²
	2X	9X	6.78X	1.41=	172.08m ²
					1299.22m ²

Continuation

Continuation
C: D -

RS. 8,63,313.00

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
B. f.	—				RS. 8,63,313.00
less 0.11% below					— RS. 950.00
					RS. 8,62,363.00

~~Sum~~
16/04/2025
J.E.

Material Statement

Groutwork - 97.57 m³

Emulsion - 31 kg

Bitumen - 208 kg

Stone - 2.617 m³

~~Sum~~
16/04/2025
J.E.