

3rd year maintenance

37

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
wave of north, point of road					
from Korne padmou path to					
Takya path					
Agency - Borey Bihon'					
Agreement no - 113300/2019-20					
Actual Completion - 16.01.2022.					
<u>Revised Entry</u>					
(1) Restoration of soil cut with soil					
9x 5.40 x 0.95 x 0.20 =					13.85
6x 7.45 x 0.80 x 0.30 =					8.05
8x 6.90 x 1.10 x 0.30 =					12.94
7x 5.60 x 1.05 x 0.30 =					12.35
7x 4.60 x 1.125 x 0.30 =					10.82
				Total	58.06 _{m²}
(2) point of southern x shoulder - old -					
2x 9x 5.80 x 0.90 =					93.96
2x 7x 6.60 x 1.10 =					101.64
2x 9x 5.90 x 0.85 =					90.27
2x 7x 4.20 x 0.55 =					36.19
				Total	322.06 _{m²}

Continuation

17. Payments now to be made, as deta

Scanned with CamScanner