

3rd Year maintenance

33

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
1. Name of work: To 3 to 11/12/2019					
Tola Rampur Bhagaur under					
mm 454 (sc)					
2. Name of Agency: Braj Bihari					
3. Agreement No: 12/350/2019-20					
4. Actual dt. of completion: 22.08.2020					
work done					
① Restoration of drains					
with soil - curb					
2x 10.80 x 1.0 x 0.30 = 6.48					
3x 20.60 x 0.90 x 0.30 = 16.686					
4x 20.70 x 0.75 x 0.25 = 19.875					
					17.368
					40.559
					40.47m ³
② Maintenance of garden					
shoulder - curb					
3x 10.80 x 1.0 = 32.40					
4x 20.60 x 0.90 = 74.16					
3x 10.60 x 0.82 = 26.076					
4x 10.82 x 0.75 = 32.46					
5x 10.60 x 0.65 = 34.45					
2x 12.50 x 0.80 = 20.0					
1x 10.60 x 0.50 = 5.30					
					224.846m ²
					224.83m ²
③ Repair to pot hole only					
seal surfacing curb					
5x 1.90 x 0.70 = 6.65m ²					
2x 1.70 x 1.0 = 3.40m ²					
Continuation					
2.00 x 5.00 = 10.00m ²					

P.T.O.

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
			B.P.R.	6519	5200
⑥/6 maintenance of					
hume pipe culvert					
—			clw - R.C.		
Qty =	1.0	NO	hole m.B.		
			page 34		
⑦/6 1102 = 81/each — R					110320
⑦/9 maintenance of room					
2 km stone culvert					
Qty =	0.57	2 km	hole		
			TM B page 34		
⑧/6 1054 711 = 43/km — R					40600
⑧ providing & laying					
5 of hot applied thermo.					
plastic compound 2.5					
mm thick duct					
Qty =	117.20	m ²	vide		
			TM B page 34		
⑨/6 735240/m ² — R					8398300
				R	15068700
Add 1% labour cost — R					150700
Add 12% Cr. S. — R					1808200
				R	17027600
Less 10.0% below Cr. R				R	1702800
				R	15324800

2/10/2025
01.07
J.R.

Continuation

18/11/25
A.E.