

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
<u>3rd year maintenance</u>					
<u>Name of work:- Construction of</u>					
<u>Road from char/9 Bhusauls.</u>					
<u>Road to Devi Ray ke Tola.</u>					
<u>under PMGSY SC</u>					
<u>Agency. Ratnesi Kumar Singh.</u>					
<u>At Palsari dayal Motihari-</u>					
<u>Agreement No- 58 SBD/2018-19</u>					
<u>Date of work order 20/12/18</u>					
<u>Date of Completion 19/12/2019</u>					

Details of measurement1. Restoration of RainCut with Soil do

$$2 \times 30m \times 2 \times 1.30 \times 0.30 = 46.8m^3$$

$$3 \times 10m \times 2 \times 1.25 \times 0.30 = 22.5m^3$$

$$2 \times 10m \times 2 \times 1.35 \times 0.30 = 16.20m^3$$

$$\Sigma 85.5m^3$$

$$\Delta = 85.33m^3$$

2. making up loss ofmaterial Earthen Shoulder

$$2 \times 10.5 \times 2.00 = 42.0m^2$$

$$2 \times 9m \times 2.10m = 37.8m^2$$

$$79.8m^2$$

$$\Delta = 75.25m^2$$

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Materials Statement					
Soil -	75.28	m ³			
53mm to 22.40mm	2	1.252	m ³		
11.2mm to Gr-III		0.248	m ³		
Crushed Stone		0.374	m ³		
Crushed Sand -		0.083	m ³		
18/11					
26/07/24					
RS					

ABSTRACT OF COST

1. Restoration of Rain					
Cuts - do -					
VTMB P- 51					
- 85.33 m ³ @ 38368.25/m ³					
					= 31166 =
2. making up loose of					
materials Earthen Shoulder					
VTMB P- 51					
- 75.25 m ³ @ 54371/m ³					
					= 4091 =
3. Repair of Pot hole					
Bitumen Surface road					
Road Repair - do -					

Continuation

35257/2

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
VTMB P-52					
-14.06 m ² @ R=286=77/m ²					
				R=	4032=
4. Maintenance of WBM					
do eg- 75 mm do					
VTMB P-52					
-13.80 m ² @ R=379=47/m ²					
				R=	5236=
5. Patch Repair 20 mm					
Premix Carpet etc					
VTMB P-52					
-13.875 m ²					
@ R=271=01/m ² R=					3760=
6. Maintenance of Road					
Signs -do eg					
VTMB P-52					
-2.99 km @ 1087=63/4m					
				R=	3252=
7. Plv Water Based					
Camel paint Road					
marking - camel do					
VTMB P-52					
-210 m ²					
@ R=104=91/m ² R=					22031=
8. Plv Langing Hot Applied					
Thermo plastic paint					
Continuation					73568 1/2

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
VTMB P- 53					
- 250 m ² @ 867.77/R ₂					216942 =
9. maintenance of 200 m					
Stone do do -					
VTMB P- 53					
- 0.225 km @ 749.00 R ₂					1682
10 Trimming of Grass and Weeds do do.					
VTMB P- 53					
- 609.53 m ² @ 2220/m ² R ₂					1340.2
11. White washing of					
Perimeter wall do -					
VTMB P- 53					
- 1531 m ² @ 1628/m ²					
				R ₂	257.00
				T = R ₂	2,92275 =
less. 0.18 % below					
Agreement				R ₂	526.00
				T = R ₂	2,91749 =
Attn					
26/07/24					
TS					

Continuation