

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work:- Maint. of road from					
Rupdia Panchsy road Vishwana					
manro to Furbi Karogahiya.					
Agency:- M/S - Anand Construction.					
Agg. No:- 485 Bb/mmsy/2020-21.					
Actual completion date:- 18/02/2022.					
Record Entry					
1. Restoration of					
draincuts - do -					
	8 X	6.42	X 1.12	X 0.30	= 17.412 m ³
	12 X	7.24	X 1.16	X 0.30	= 32.774 m ³
	10 X	6.10	X 1.15	X 0.30	= 21.05 m ³
					71.21 m ³
2. Making up of earth					
Shoulders - do -					
	2 X 9	X 4.56	X 1.34	=	109.99 m ²
	2 X 7	X 6.28	X 1.32	=	116.05 m ²
	2 X 6	X 5.81	X 1.29	=	89.94 m ²
	2 X 5	X 6.41	X 1.24	=	79.48 m ²
					395.46 m ²
3. Repair of potholes					
with 75 mm WBM - do -					
	7 X	3.16	X 1.08	=	23.89 m ²
	5 X	4.88	X 1.12	=	27.33 m ²
	4 X	3.67	X 1.32	=	19.38 m ²
					70.60 m ²

Continuation

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(11).	Restoration of				
	drain cuts do-				
71.21 m ³	vide T.m. B P (32)				
	RS. 350.58/m ³ — RS. 27101.00				
.	making up of				
	earth on shoulders do-				
5.46 m ²	vide T.m. B P (32)				
	RS. 5860/m ² — RS. 23174.00				
(13).	Repair of potholes do-				
	with w.b.m				
70.60 m ²	vide T.m. B P (32)				
	RS. 329.31/m ² — RS. 23254.00				
(414).	Repair of potholes				
	removal of failed mat. do-				
70.60 m ²	vide T.m. B P (33)				
	RS. 417.59/m ² — RS. 29482.00				
(515).	patch repair curbs				
	potholes do-				
70.60 m ²	vide T.m. B P (33)				
	RS. 312.50/m ² — RS. 22062.00				
(612).	Maint. of slab				
	current do-				
3 No.	vide T.m. B P (33)				
	RS. 2309.03/each — RS. 6927.00				
(719).	Maint. of road				
	signs do-				

Continuation

Continuation