

મમલકાતી ધોળા મે ઘમલ મલકા
મલકા મલકા મલકા મલકા

Schedule XLV-Form No.-134

કાર્યપાલક અધિકારી

ગ્રામીણ કાર્ય વિભાગ

કાર્ય પ્રમંડલ નેત્રકલિયાનં

DIVISION

પત્રકલિયા

SUB-DIVISION

MEASUREMENT BOOK

M.B.N. 1205/2020-21

જો મે 2020-21

Particulars

Contents of area

School Completion - 18.04.2021

$$3 \times 4.60 \times 1.80 \times 0.30 = 7.452$$

5	4.15	1.75	0.302	10.899
---	------	------	-------	--------

total = 33.742

2	x	6	x	5.20	x	2.10	2	131.04
---	---	---	---	------	---	------	---	--------

Qty	297.60
-----	--------

34 3.30 x 1.75 = 17.325 m²

total flux — 0.600 K4.

Sch. XLV-Form No. 134 30

Continuation

Continuation

Continuation

3rd year maintenance

37

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work - Paint of road from					
1st 100 to Saman Bhagat					
manjhi.					
Agency - M/s Ranjan Const.					
Agg. No - H.S.B./2020-21.					
Date of start - 30/01/2020.					
Actual completion - 18/04/2021.					
<u>Record Entry</u>					
1. Restoration of					
rain cuts - do -					
6 X 4.50 X 2.10 X 0.30 =					17.01 m ³
8 X 3.90 X 1.70 X 0.30 =					17.78 m ³
5 X 6.60 X 1.25 X 0.30 =					12.38 m ³
					47.17 m ³
2. Making up of gutter					
Shoulder - do -					
2 X 6 X 8.50 X 1.60 =					163.20 m ²
2 X 4 X 6.90 X 1.90 =					104.88 m ²
2 X 5 X 4.90 X 1.80 =					88.20 m ²
2 X 6 X 4.90 X 1.05 =					61.74 m ²
					418.02 m ²
3. Repair of pot holes					
filled with 15 mm					
W.B.M - do -					
6 X 2.55 X 1.20 =					18.36 m ²
9 X 4.00 X 0.95 =					34.20 m ²
					52.56 m ²

Continuation

Continuation:

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
<u>Material Statement</u>					
Earthwork -					47.17 m ³
Emulsion -					0.018 m ³
B.T -					0.113 m ³
Stone -					1.419 m ³
Sand -					0.315 m ³
R.D.					
08/11/24					
J.E.					

<u>Good yr. maint.</u>					
Vr. no. of					
Memo for pay of Rs. -	350036	2	00	00	00
T. Tax - 2%	7001	2	00	00	00
U. Tax - 1%	3500	2	00	00	00
S. (4.5%) - 1%	3500	2	00	00	00
C. (4.5%) - 1%	3500	2	00	00	00
Roy -	3554	2	00	00	00
S.F. -	1538	2	00	00	00
Total Ded -	22596	2	00	00	00
By CRMS -	327440	2	00	00	00
Gross -	350036	2	00	00	00
Passed for Rs. -	350036	2	00	00	00
Three Lakh fifty thousand					
thirty six only					

4th year maintenance

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work:- Maint. of road from Lal Tola to Saman Bhogat manjhi.					
Agency :- M/s Ranjan Construction.					
Agg. No :- 11 SBB/2020-21.					
Actual completion Dates:- 18/04/2021.					
<u>Record Entry</u>					
1.	Restoration of raincuts do-				
	$2 \times 3 \times 30.00 \times 1.00 \times 0.30 = 54.00m^3$				
2.	Making up of earthen shoulder do-				
	$2 \times 7 \times 30.00 \times 1.13 = 474.60m^2$				
3.	Repair of potholes with 75mm W.Bm do-				
	$12 \times 6.73 \times 0.87 = 70.26m^2$				
4.	patch repair over potholes do-				
	Qty. same as above				
	Item =				$70.26m^2$
5.	Maint. of road steps do-				$0.60km$
6.	Maint. of 200m of km stone do-				$1.20km$
7.	Trimming of grass and weeds do-				
	$2 \times 12 \times 30.00 \times 1.04 = 748.80m^2$				

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
8. Maint. of trees by road sides - do -					375 Nos.
 PRK 2410675 313 2715 5715 (25) 					
<u>Material Statement</u>					
earthwork = $54.00m^3$					
Emulsion = 22 kg					
Bitumen = 151 kg					
Stone chips = $1.90m^3$					
Stone metal = $1.41m^3$					
PRK					

<u>Abstract of cost</u>					
(11).	Restoration of				
	saw cuts - do -				
$54.00m^3$	vide T.m.B.P.	(12)			
	RS. 386.14/ m^3		RS.	20852.00	
(212).	making up of				
	earthen shoulder - do -				
$474.60m^2$	vide T.m.B.P.	(12)			
	RS. 57.56/ m^2		RS.	27318.00	
(313).	Repair of potholes				
	with 75mm W.B.M. - do -				
$70.26m^2$	vide T.m.B.P.	(12)			
	RS. 403.80/ m^2		RS.	28371.00	
(414).	patch repair over				
	potholes - do -				

[illegible]

Continuation