

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
n/w :- cons. of Road from					
Bangal Pmasy to Repigach					
Agg no :- 21/mmsy/000/2019-20					
Agencg :- m/s Balbom cont.					
Actual completion - 06/8/2020					

Record Measurement

1) Restoration of Rainwater

8	30.0	0.90	0.30	64.80 m ³
5	20.0	0.90	0.30	27.00
4	10.0	1.25	0.30	15.00
2	15.0	1.25	0.30	11.25
				118.05 m ³

2) making up of Brm/shoulder

15	30.0	1.00	-	450.00 m ²
4	28.0	1.00	-	112.00
10	30.0	1.00	-	300.00
5	18.0	1.00	-	90.00
10	10.0	1.00	-	100.00
8	20.0	1.00	-	160.00
				1212.00 m ²

3) maints of w.p.m Road

1	10.20	3.10	-	31.62 m ²
1	8.40	1.80	-	15.12
1	15.00	2.50	-	37.50
1	12.00	1.50	-	18.00
1	9.50	2.00	-	19.00
1	8.70	1.40	-	12.18

Continuation

1	10.50	1.20	-	18.90
				152.32 m ²

Abstract of cost

76

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
1) Resubstitution of Raincuts					
vide Tim. B Page (74) itm (1)					
118.05 m ² @ 380.52 /-				h	44922 =
2) Making up of Berms/shoulder					
vide Tim. B Page (74) itm (2)					
1212.0 m ² @ 58.32 /-				h	70744 =
3) Maints of w.B.m Road					
vide Tim. B Page (74) itm (3)					
152.32 m ² @ 427.71 /-				h	65149 =
4) Maints of Bitumina m.s.s					
vide Tim. B Page (75) itm (4)					
152.22 m ² @ 259.60 /-				h	39542 =
5) Maints of m. work (H.P.)					
do - all - c - job					3-0-100
vide Tim. B Page (75) itm (4)					
3.00 m ² @ 112.00 /-				h	3351 =
6) Maints of Road Sign.					
do - all - c - job					0-36 an
vide Tim. B Page (75) itm (5)					
0.36 m ² @ 1074.51 /-				h	387 =
7) Maints of Drain A in situ					
do - all - c - job					0-50 an
vide Tim. B Page (75) itm (6)					
0.58 m ² @ 573.26 /-				h	333 =
8) cutting of branches of Trees					
A Shrub - c - job					0-0-100
vide Tim. B Page (75) itm (7)					
3.00 m ² @ 106.52 /-				h	320.0

Continuation

[illegible]