

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमंडल, सहरसा

Email ID:-ee.saharsa.rwd2@gmail.com

Mob:- 8986915395

पत्रांक.....21.263/20 सहरसा/दिनांक 23.9.25

प्रेषक,

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, सहरसा

सेवा में,

नोडल पदाधिकारी (MR 3054)
ग्रामीण कार्य विभाग
पटना, बिहार

विषय :- नई अनुरक्षण नीति-2018MR (3054) योजना के अंतर्गत पथों में कराये गये कार्य के विरुद्ध हेतु आवंटन उपलब्ध कराने के संबंध में।

महाशय,

उपरोक्त विषय के संबंध में सूचित करना है कि नई अनुरक्षण नीति-2018 MR (3054) योजना के अंतर्गत पथों में कराये गये कार्य के लिए संवेदक को भुगतान करने हेतु अधियाचना विहित प्रपत्र में भरकर आवश्यक कार्यवाही हेतु समर्पित की जा रही हैं।

अतः अनुरोध है कि पथों में कराये गये कार्य हेतु आवंटन उपलब्ध कराने की कृपा की जाए।

अनु :- यथोक्त।

विश्वासभाजन

23/9/25

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, सहरसा।

23/9/25

FORM GFR 19-A

(See Government of India's Decision (I) below Rule-150)

Form of Utilization Certificate up to September 23, 2025


Sl.No	Name of Scheme	Sanction No.&Date With Amount (In lace Rs.)	Amount Received (In lace Rs.)	Particulars
1	Construction of Rural roads Under "New Maintenance Policy-2018 MR (3054)"	New Maintenance Policy-2018 MR (3054) BRRDA PATNA Lt no-81 Dt-19.09.2025	9075.00538	Certified that out of Rs.9075.00538Lac of grants-in-aid sanctioned during the years 2025-26. In favor of EE,RWD Works Division Saharsa a sum of Rs. 8779.95632 lac has been utilized for the purpose of MR (3054) Schemes as given in the margin for which it was sanctioned and that the balance of Rs. 295.04906 Lac remaining unutilized at the end of the period under report.
	Total:		9075.00538	

6. Certified that I have satisfied myself that the conditions on which the grant-in-aid was sanctioned have been duly fulfilled/are being fulfilled and that I have exercised the following checks to see that the money was utilized for the purpose for which it was sanctioned.

Kind of Checks exercised:-

- xi. Works have been supervised by Executive Engineer/ Superintending Engineer.
 - xii. Periodical inspection has been conducted by Executive Engineer/ Superintending Engineer.
 - xiii. Construction materials have been tested.
 - xiv. Measurements have been recorded in the MBs and test check conducted by the Assistant Engineer/ Executive Engineer.
 - xv. All other caudal formalities have been observed.
7. **Physical Progress achieved:-**
- iii. Construction of Road Works.
 - ii. Construction of CD works.


Divisional Accounts Officer
R.W.D, works Division
Saharsa.


Executive Engineer
R.W.D, works Division
Saharsa.

Rural Works Department
MR NEW MAINTENANCE POLICY-2018 REQUISITION

Name of Division:- RWD Works Division Saharsa

Sl. No.	Year	Name of Road	Name of Contractor (in English)	Project Id	Administrative Sanction		Agreement Amount (In Lacs)		Value of IRI (in mm/km)	Thickness of Bitumen Layer (in mm)	Value of Bitumen Content in Percentage	Allotment Received (in Lacs)	Total Expenditure as per MIS (in Lacs)	Value of Measurement (in Lacs)	Current Demand (in Lacs)	Remarks
					Length (in KM)	Amount (in Lac)	Main Work Amount	Maintenance Amount								
1	2023-24	LO36-SISAI To Sahpur (VRI)	Deo Contractors Private Limited	20904302162	1.473	79.03000	52.01363	14.65970	3551	25mm	5%	0.00000	0.00000	52.01363	52.01363	
2	2023-24	Kumharghat Adhwaan Road To Bada Field	Deo Contractors Private Limited	20904313042	0.960	28.97300	16.47758	8.34680	3323	25mm	5%	0.00000	0.00000	16.47758	16.47758	
Total					2.433	108.00300	68.49121	23.00650				0.000	0.000	68.49121	68.49121	

Rural Works Department
Works Division, Saharsa

Executive Engineer
Rural Works Department
Works Division, Saharsa

Name of Road:- L036-Sisai to Sahpur (VR3)

Name of Contractor:- Deo Contractors Private Limited

Date	Time	Section No.	Length in km	Bumps in mm	Speed Rate	OR mm/km	IRI mm/km	CATEGORY ROAD	Latitude	Longitude	Event
18/9/25	8:52:0	64	0.1	280	0	2800	3361 G		25.997881	86.554648	Normal
18/9/25	8:52:0	64	0.1	300	10.1	3000	3588 G		25.997948	86.554865	Normal
18/9/25	8:52:0	64	0.1	320	20.2	3200	3816 G		25.997948	86.554865	Normal
18/9/25	8:52:0	64	0.1	320	20.2	3200	3816 G		25.998855	86.554877	Normal
18/9/25	8:52:0	64	0.1	290	30.3	2900	3475 G		26.000668	86.553537	Normal
18/9/25	8:52:0	64	0.1	300	30.3	3000	3588 G		26.000718	86.554132	Normal
18/9/25	8:52:0	64	0.1	280	40.4	2800	3361 G		26.00275	86.55436	Normal
18/9/25	8:52:0	64	0.1	310	40.4	3100	3702 G		26.002748	86.554572	Normal
18/9/25	8:52:34	64	0.1	310	40.4	3100	3702 G		26.005607	86.558842	Normal
18/9/25	8:52:34	64	0.1	290	50.5	2900	3475 G		26.00649	86.553447	Normal
18/9/25	8:52:34	64	0.1	270	40.4	2700	3243 G		25.997881	86.554648	Normal
18/9/25	8:52:34	64	0.1	300	40.4	3000	3588 G		25.997948	86.554865	Normal
18/9/25	8:52:34	64	0.1	290	30.3	2900	3475 G		25.997948	86.554865	Normal
18/9/25	8:52:34	64	0.1	290	30.3	2900	3475 G		25.998855	86.554877	Normal
18/9/25	8:52:34	64	0.07	210	40.4	3000	3588 G		26.00649	86.553447	Curve
Average IRI							3551				

$$Y = 0 * X^2 + 1.136 * X + 181$$

$$X = 1667$$

$$Y = 2074$$

(R) RURAL ROAD

Good Average Poor


<4000 4001-5000 >5001

fake it
Pmsm
22/09/25
15

Sp. J.
22/09/25
K

23/9/25

File : E:\Steco Bumb Indicator Report\August 25\18092859.Xls, Section No. : 64, Eqn : $Y = 0 * X^2 + 1.136 * X + 181$
 Name of Customer : Deo Constructors Pvt Ltd, Name of Work/ Road : L036-Sisai to Sahpur, Lab Job number : 64



Pakish
 29/09/25
 TS

G. S. S.
 22/09/2025
 KE

P. S. S.
 23/09/25

अधियाचना हेतु प्रमाण-पत्र

प्रमाणित किया जाता है कि नई अनुरक्षण नीति-2018 योजनान्तर्गत:-

1. पथ एल036-सिराई से सहपुर (VR3) में कराये गये कार्य की गुणवत्ता जाँच की गयी है जो निर्धारित मानक/विशिष्टियों के अनुरूप हैं।
2. अद्यतन कराये गये कार्य की मापी पुरतिका में दर्ज है जिसका सत्यापन कर लिया गया है।

Rajesh
22/09/2025
नई

कनीय अभियंता
ग्रामीण कार्य विभाग
कार्य प्रशाखा, सत्तर कटैया।

22/09/2025

सहायक अभियंता
ग्रामीण कार्य विभाग
कार्य अवर प्रमंडल,
सत्तर कटैया।

22/09/25

कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल, सहरसा