

3rd year maintenance

59

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of Work: - Construction of					
Road from Kamta Bazar to					
Ragauli to Pakhalgaon					
Agency - Annavi Construction.					
Agreement No. - 72 SBD / 2020 - 21					
Date of start - 20.7.2020					
Date of Completion - 30.1.2022					

measurements

① Restoring of Rain Cut					
with all complete jobs					
3 X	2.4m	X	.80	X	.30 = 1.728 m ³
2 X	1.80	X	.90	X	.30 = 0.972 m ³
1 X	3.25	X	.75	X	.25 = 0.609 m ³
5 X	2.1	X	.60	X	.30 = 1.89 m ³
2 X	2.75	X	.75	X	.45 = 1.85 m ³
4 X	3.45	X	.90	X	.30 = 3.72 m ³
2 X	1.80	X	.75	X	.25 = 2.675 m ³
1 X	2.95	X	.60	X	.30 = 1.53 m ³
8 X	2.60	X	.80	X	.40 = 6.65 m ³
4 X	2.75	X	.75	X	.35 = 2.88 m ³
3 X	3.25	X	.60	X	.25 = 1.75 m ³
3 X	4.15	X	.80	X	.35 = 3.48 m ³
Total =					26.146 m ³
Limit					26.05 m ³

② Making up of Shoulder
with all complete jobs

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
8 x 15.25 m x 0.90 m =					41.175 m
4 x 11.75 m x 0.75 m =					35.25 m
3 x 14.50 m x 1.00 m =					43.50 m
1 x 8.35 m x .80 m =					1.67 m ²
Total =					121.595 m
Limit =					120.23 m ²

③ Repair of pot hole

with as complete

job

1 m²

④ patch repair over pot

hole with as complete

job

3 x	1.25 x	.90 =	3.45 m ²
2 x	1.12 x	.75 =	1.68 m ²
3 x	.90 x	.80 =	2.16 m ²
4 x	1.35 x	.85 =	3.81 m ²
7 x	1.85 x	.75 =	9.71 m ²
⑤ 1 x	1.50 x	.60 =	0.90 m ²
Total =			21.41 m ²

⑤ patch repair over

bituminous surface with

as complete job

Qty vide Item No ④

Page - ⑥0

21.41 m²

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
⑥ Maintenance of C.D. with all complete		2.16			
⑦ Maintenance of road Spm		0.95 Km			
⑧ maintenance of 200m & 1cm stone		1.7 Km			
⑨ Cutting of branches of tree		1 No			
⑩ Cutting of shrubs with all		2 No			
⑪ Trimming of grass with all		2.70 m ²			
⑫ Maintenance of tree on road side		4.8 No			
10/07/21 J.B. 10/07/21 A.E.					

Continuation

Abstract of Est.

62

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
① Restore of Rtn Cut with as					
Tim B.V.P. (59)		28.05	m ³		
② 386.14/m ³				Rs = 10059/-	
② maring up of boulder					
Tim B.V.P. (60)		120.23	m ³		
③ 57.36/m ³				Rs = 6896/-	
③ Repair of patch hole with as					
Tim B.V.P. (60)		2.44	m ³		
④ 12333.42/m ³				Rs = 12333/-	
④ patch repair over pot cut					
Tim B.V.P. (60)		21.4	m ²		
⑤ 340.49/m ²				Rs = 7290/-	
⑤ patch repair over bituminous					
Tim B.V.P. (60)		21.4	m ²		
⑥ 353.11/m ²				Rs = 7560/-	
⑥ Maintenance of c.d					
Tim B.V.P. (60)		2329.00	m ⁰		
⑦ 2329.00/m ⁰				Rs = 2329/-	

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
⑦ Maintenance of Road Sign					
Time B.V.P (6)		0.95 km			
②	1027.82 / km			Rs. 1023/-	
⑧ Maintenance of 200m x 1cm stone					
Time B.V.P (6)		.17 Km			
②	628.24 / 17m			Rs. 107/-	
⑨ Cutting of branches of tree with ax					
Time B.V.P (6)		1.16			
②	109.24 / 1.16			Rs. 110/-	
⑩ Cutting of shrubs with ax					
Time B.V.P (6)		5.16			
②	6.73 / 1.6			Rs. 34/-	
⑪ Trimming of grasses					
Time B.V.P (6)		2.70 m ²			
②	2.24 / m ²			Rs. 6/-	
⑫ Maintenance of tree					
Time B.V.P (6)		4.61 m			
②	674.37 / 1.6			Rs. 3102/-	
Continuation					
Total Rs. 78768/-					

Continuation