

3rd year Maintenance

19

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
M/W- Maint. of Road from					
Dahila to Parsuagar Pachim					
to/ Hote Hual Basopatti					
Sima.					
Agry- Sri Arvind Thakur					
Ag. No- 40- SB 71 19-20					
Pl. start- 21/9/19					
Act. Compli- 26/5/22					

Measurements

(1) Restoration of Rain-luts with Soil; Marrym etc as per specification.					
5x	15.0m	x	0.90	x	0.300
8x	11.0m	x	1.30	x	0.300 = 20.25m ³
3x	22.0m	x	1.25	x	0.300 = 24.75m ³
5x	2x 7.0m	x	1.10	x	0.300 = 23.10m ³
12x	10.0m	x	0.70	x	0.300 = 25.20m ³
9x	3.0m	x	0.90	x	0.300 = 7.30m ³
7x	17.0m	x	0.75	x	0.300 = 26.78m ³
12x	5.0m	x	1.30	x	0.300 = 23.40m ³
8x	10.0m	x	1.00	x	0.300 = 24.00m ³
				Total = 174.78m ³	

Continuation

3rd year

22

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Abstract of Cost.					
(1) Re. for. of Rain-cuts					
Wid. 1m. 15, Hm-1, P-19					
= 174.78 m ³					
@ Rs 380.58/m ³ - Rs					66,518 =
(2) Maint. of Shoulders					
Wid. 4m. 2, P-20					
= 927.23 m ²					
@ Rs 58.37/m ² - Rs					54,122 =
(3) Pl. of 5mm. B.m.					
Wid. 4m. 3, P-20 = 10.73 m ²					
@ Rs 1134.50/m ² - Rs					12,174.2 =
(4) Patch Repair of Pot holes					
Wid. 1m. 4, P-20 = 148.0 m ²					
@ Rs 293.73/m ² - Rs					42,008 =
(5) Maint. of H/P Culverts					
Wid. 4m. 5, P-21 = 0.4 Nos.					
@ Rs 1117.0/cu - Rs					4468 =
(6) Maint. of S/cu Culverts					
Wid. 4m. 6, P-21 = 0.4 Nos.					
@ Rs 2309.04/cu - Rs					9236 =
(7) Maint. of Road Signs					

Continuation

298689 =

Continuation