

3rd Year Maintenance

8

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work - Maintenance of road from H/D Bhagat Pathak to Muslim Tola under GTSNY Agency - M/S Nikumbh Bhardwaj Constn					
Agreement No - 48 SBD/2019-20					
Date of start - 22/03/2020					
Date of completion - 21/03/2021					
Actual date of completion - 13/01/2022					
3rd Year Maintenance Period } 14/01/2024 13/01/2025					
① Maintenance of earthen shoulder					

1	X	8.50	X 1.20 =	10.20m ²
2	X	10.40	X 1.20 =	24.60m ²
2	X	7.40	X 1.25 =	17.50m ²
2	X	8.40	X 1.20 =	19.20m ²
1	X	6.15	X 0.90 =	5.53m ²
2	X	6.50	X 1.28 =	16.64m ²
1	X	9.10	X 1.20 =	10.92m ²
3	X	7.50	X 1.15 =	25.87m ²
2	X	7.40	X 1.28 =	17.92m ²
2	X	10.50	X 1.20 =	25.20m ²
3	X	6.40	X 1.10 =	19.80m ²
5	X	11.40	X 1.20 =	66.40m ²
4	X	20.40	X 1.15 =	92.40m ²
4	X	9.60	X 1.10 =	42.24m ²
				393.02m ²

Continuation

Abstract of cast

10

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	

(1) Restoration of Rain cuts

$$Q-VTNB/9(2) = 81.087$$

$$e R 378.3217^2 - R - 30674 = 0$$

(2) Maintenance of earthen shoulder

$$Q-VTNB/8(1) = 393.027^2$$

$$e R - 57 = 3517^2 R - 22540 = 0$$

(3) Maintenance of H.P. culvert

$$Q-VTNB/9(3) = 1 \text{ Nag}$$

$$e R 1109 = 67/100 R - 1110 = 0$$

$$R - 54329 = 0$$

$$L. 2.75 \text{ below } 1494 = 0$$

$$R - 52830 = 0$$

26/03/25
JE

26/03/25
RE

material statement

$$Soil - 119.7677$$

26/03/25
JE

Continuation
26/03/25
RE