

5

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
	<u>Abstract of cost</u>				
Item w-1 Restoration of main ent do-do all pl-					
vide Ygn - 2 = 993.76 m ²					
Level 325.42 m ² e R 359.74/m ² — B					117072 = ∞ <u>120066 = ∞</u>
Item w-2 Making up to Berms Shoulder do-do all pl-					
vide Ygn - 3 = 1847.25 m ²					
Level 1239.75 m ² e R 53.68/m ² — B					66550 = ∞ <u>991652 = ∞</u>
Item w-3 Patch repair over bituminous surface with 10mm concrete carpet					
vide Ygn - 4 = 297.76 m ²					
e R 213.54/m ² — B					52906 = ∞
Item w-4 Maintenance of C/D work Main pipe do-do all R3					
vide Ygn - 4 = 4 nos					
e R 1104.35 — B					4417 = ∞
Item w-5 Maintenance of C/D work Slat culvert do-do all R3					
vide Ygn = 3. nos					
e R 2287.21 — B					6862 = ∞
Total B →					283416 = ∞ <u>230510 = ∞</u>
Deduction					
Less 10% below as per Agreement					23051 = ∞ <u>28341 = ∞</u>
Grand Total					B 255075 = ∞ B 207459 = ∞

Continuation

[illegible]

