

Agency

11. Highway (1 point)

1847-1848

PLATE 4.

~~E. E. R. W. D. W. O. or~~ **DIVISION**

The Netherland
— **500-1000**

三才圖會

4111

Particulars	Details of actual measurement				Contents of area
	No.	L	B	D	

4th year main

Name of work - To change

Road path to Nenua

Agency - Sri Ramesh Krishna

(1) Restoration of Rain cuts

Berm with Soil

— 010 — Completed

$$2 \times 2 \times 14 \times 100.30 = 16.80 \text{ m}^3$$

$$1 \times 2 \times 11.50 \times 0.30 = 6.90 \text{ m}^3$$

$$2 \times 2 \times 8.25 \times 100.30 = 10.02 \text{ m}^3$$

$$1 \times 2 \times 12.00 \times 100.30 = 7.20 \text{ m}^3$$

$$1 \times 2 \times 11 \times 100.30 = 6.60 \text{ m}^3$$

47.20 m³

(2) Repairing of berm

Shoulder stripping excess

Soil from the Shoulder

— 010 — Completed

$$2 \times 2 \times 14 \times 1 = 56.00 \text{ m}^3$$

$$2 \times 2 \times 16 \times 1 = 64.00 \text{ m}^3$$

$$2 \times 2 \times 22 \times 1 = 88.00 \text{ m}^3$$

$$2 \times 2 \times 16.25 \times 1 = 65.00 \text{ m}^3$$

$$2 \times 2 \times 20 \times 1 = 80.00 \text{ m}^3$$

33.00 m²

(3) Repairing pot holes

filled with 25 mm WBM

— 010 — Completed

0.00

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L	B	D	
<u>Item no.1 (S)</u>					
10x2.25x2.25x0.05					4.64m ²
10x2.05x2.25x0.05					3.46m ²
12x2.25x2.25x0.05					5.59m ²
9x3.05x2.12x0.05					4.10m ²
9x3.05x2.12x0.05					4.44m ²
8x3.25x3.05x0.05					5.94m ²
10x2.05x2.25x0.05					3.46m ²
10x2.05x2.25x0.05					3.46m²
10x3.25x3.05x0.05					7.22m ²
8x2.15x2.35x0.05					3.65m ²
9x2.05x2.25x0.05					3.46m ²
10x2.15x2.25x0.05					3.79m ²
12x2.18x2.25x0.05					5.40m ²
10x2.35x2.05x0.05					3.65m ²
					58.10m ²
(4) patch Repair over bituminous Surface with 20mm bit Seal Surface					
<u>Complete Job</u>					
10x2.25x2.25x0.05					4.64m ²
10x2.05x2.25x0.05					3.46m ²
12x2.25x2.25x0.05					5.59m ²
9x2.65x2.25x0.05					4.10m ²
9x3.05x2.12x0.05					4.43m ²
8x3.25x3.05x0.05					5.96m ²
10x3.25x3.05x0.05					7.22m ²
10x2.05x2.25x0.05					3.66m ²
8x2.15x2.35x0.05					3.65m ²
					42.40m ²

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L	B	D	
				40 m	
99 2.05 2.25 0.45 2.25					
109 2.15 2.25 0.45 2.25					
129 2.18 2.25 0.45 2.25					
109 2.35 2.40 0.45 2.65					
(4) Patch Repair over					
bifuminous surface					
with polymer mule seal					
Surface					
210 - Comp Job					
1.25 2.75					3.44 m
2.05 2.25					4.61 m
2.75 2.26					6.21 m
2.85 2.25					5.96 m
3.03 2.17					6.57 m
2.15 2.05					6.56 m
2 2.25 2.01					19.56 m
2.19 2.36					5.14 m
					58.10 m
(5) maintenance of					
20 (Hume pipe culvert)					
2 nos					
(6) maintenance of 200m					
2nd km Stone					
0.15 km					
(7) maintenance of					
Road Siph					
0.1 km					

Continuation

Continuation

