

628/21-22

# Schedule XLV-Form No. 134

310721 92412 327

प्रमाणित और रिपोर्ट के लोयस (H.M. 159) से  
(वर्गवार संशोधन अर्थ)

310721

DIVISION

310721

SUB-DIVISION

## MEASUREMENT BOOK

971 480 5311 4810 सिफ

# 4<sup>th</sup> Year Maintenance.

21

Sch. XLV-Form No. 134

| Particulars                                                                     | Details of actual measurement |          |                      |                      | Contents of area |
|---------------------------------------------------------------------------------|-------------------------------|----------|----------------------|----------------------|------------------|
|                                                                                 | No.                           | L.       | B.                   | D.                   |                  |
| Name of work- Maintenance of road from Sikaliya Babu to 19 to 2045 under mistry |                               |          |                      |                      |                  |
| Agency- Ajay Kumar Dubey                                                        |                               |          |                      |                      |                  |
| Agreement No - 16 SBD / 2020-21                                                 |                               |          |                      |                      |                  |
| Actual date of completion- 25/02/2021                                           |                               |          |                      |                      |                  |
| 4 <sup>th</sup> Year Maintenance? 26/02/2024 to Period } 25/02/2025             |                               |          |                      |                      |                  |
| ① Restoration of Raiments                                                       |                               |          |                      |                      |                  |
| 1 x                                                                             | 7.00                          | x 1.15   | x 0.25 =             | 2.01 m <sup>3</sup>  |                  |
| 2 x                                                                             | 8.00                          | x 1.25   | x 0.30 =             | 6.00 m <sup>3</sup>  |                  |
| 2 x                                                                             | 9.00                          | x 1.25   | x 0.25 =             | 5.62 m <sup>3</sup>  |                  |
| 1 x                                                                             | 5.00                          | x 0.90   | x 0.30 =             | 1.35 m <sup>3</sup>  |                  |
| 2 x                                                                             | 10.50                         | x 1.20   | x 0.25 =             | 6.30 m <sup>3</sup>  |                  |
| 3 x                                                                             | 9.50                          | x 1.15   | x 0.25 =             | 8.19 m <sup>3</sup>  |                  |
| 1 x                                                                             | 8.50                          | x 1.20   | x 0.30 =             | 3.06 m <sup>3</sup>  |                  |
| 1 x                                                                             | 7.00                          | x 1.28   | x 0.30 =             | 2.69 m <sup>3</sup>  |                  |
| 2 x                                                                             | 7.80                          | x 1.20   | x 0.25 =             | 4.68 m <sup>3</sup>  |                  |
| 4 x                                                                             | 8.15                          | x 1.10   | x 0.25 =             | 8.96 m <sup>3</sup>  |                  |
|                                                                                 |                               |          |                      | 48.85 m <sup>3</sup> |                  |
| ② Maintenance of earthen shoulder                                               |                               |          |                      |                      |                  |
| 2 x                                                                             | 8.00                          | x 1.25 = | 20.00 m <sup>3</sup> |                      |                  |
| 1 x                                                                             | 6.10                          | x 1.20 = | 7.32 m <sup>3</sup>  |                      |                  |
| 2 x                                                                             | 7.50                          | x 0.90 = | 13.50 m <sup>3</sup> |                      |                  |
| 2 x                                                                             | 10.00                         | x 1.28 = | 25.60 m <sup>3</sup> |                      |                  |
| 2 x                                                                             | 9.00                          | x 1.25 = | 22.50 m <sup>3</sup> |                      |                  |
| 1 x                                                                             | 7.50                          | x 1.10 = | 8.25 m <sup>3</sup>  |                      |                  |

Continuation



| Particulars                 | Details of actual measurement |    |    |    | Contents of area |
|-----------------------------|-------------------------------|----|----|----|------------------|
|                             | No.                           | L. | B. | D. |                  |
| ① $R_1$ 2.29/15 - $R_1$     |                               |    |    |    | 151520           |
| ⑧ Maintenance of Trees      |                               |    |    |    |                  |
| Q. V. 1113/23 ⑧ = 60 Nos    |                               |    |    |    |                  |
| $R_1$ 509 = 45/each $R_1$   |                               |    |    |    | 3056700          |
| ⑨ Maintenance of road sq    |                               |    |    |    |                  |
| Q. V. 1113/23 ⑨ = 0.47 Km   |                               |    |    |    |                  |
| $R_1$ 1077.81/Km $R_1$      |                               |    |    |    | 50700            |
| ⑩ Maintenance of 200m stone |                               |    |    |    |                  |
| Q. V. 1113/23 ⑩ = 0.95 Km   |                               |    |    |    |                  |
| $R_1$ 702 = 29/Km $R_1$     |                               |    |    |    | 66700            |
|                             |                               |    |    |    | $R_1$ 12249300   |
| Add 1.1/1 Labour cess (+)   |                               |    |    |    | 122400           |
| Add 12.1/1 ST (+)           |                               |    |    |    | 1469300          |
|                             |                               |    |    |    | $R_1$ 13836000   |
| Less 0.1/1 below -          |                               |    |    |    | 13800            |
|                             |                               |    |    |    | $R_1$ 13822200   |
| Rs in Rs                    |                               |    |    |    |                  |
| 17/06/25                    |                               |    |    |    |                  |
| J.E                         |                               |    |    |    |                  |