

ମାପକରଣ ଓ ମାପକରଣ

ମାପକରଣ ଓ ମାପକରଣ

Schedule XLV-Form No. 134

P.W.D ବିଭାଗ

DIVISION

P.W.D - ଶାସନ

SUB-DIVISION

Measurement Book

ମାପକରଣ - 1004

5th year maintenance Bill

71

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
M/W - Kharhar to Kharhar					
Agency - Shri. Meenakshi prasad.					
Agg. No - 47582/19-20					
Start of work - 21.9.19					
Date of completion - 25/9/20					
Work done -					
① Restoration of Rain water					
Pipes with soil medium					
do do - 6 mplu					
5x15 x 0.850 x 0.30 = 19.125 m ³					
5x10 x 0.900 x 0.275 = 12.375 m ³					
3x30 x 0.700 x 0.300 = 18.9 m ³					
1x25 x 1.0 x 0.300 = 7.5 m ³					
1x30 x 1.0 x 0.280 = 8.40 m ³					
4x10 x 1.0 x 0.30 = 12.0 m ³					
3x25 x .900 x 0.30 = 20.25 m ³					
5x10 x 0.800 x 0.275 = 11.0 m ³					
7x10 x 0.900 x 0.300 = 15.40 m ³					
5x20 x 0.950 x 0.280 = 26.60 m ³					
2x10 x 0.750 x 0.300 = 9.00 m ³					
5x15 x 0.900 x 0.300 = 20.25 m ³					
					171.8 m ³
					Limit - 167.04 m ³

Continuation

Abstract of LOS

75

Sch. XLV-Form No. 134

Particulars	Details of actual measurement.				Contents of area
	No.	L	B.	D.	
① Restoration of Rain water					
vide Temp- 71					
Qty - 169.04 m ³					
@ 380.58/m ³ - Rs					64333.00
② making of Brm. Shutter					
Temp- 72					
Qty - 987.75 m ²					
@ 58.37/m ² - Rs					57655.00
③ Repair up pot hole					
filled with 75 mm Bt					
vide Temp- 73					
Qty - 11.08 m ³					
@ 11290.23/m ³ - Rs					125096.00
④ patch repair over pot					
with ms					
vide Temp- 73					
Qty - 147.77 m ²					
@ 292.71/m ² - Rs					43253.00
					51257.00
⑤ maintenance of road work					
HP - 1000					
vide Temp- 73					
Qty - 1.143					
@ 1117.00/m ³ - Rs					1117.00

Continuation

Continuation