

3rd Year Maintenance Bid

37

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
① Restoration of Rain Cuts with soil					
	2X	6.00X	2.20X	0.30 =	7.32M ³
	3X	5.50X	2.25X	0.30 =	11.14M ³
	4X	7.00X	1.90X	0.30 =	15.96M ³
	5X	4.50X	2.00X	0.30 =	13.50M ³
	6X	5.20X	1.90X	0.30 =	17.78M ³
	2X	5.30X	2.10X	0.30 =	6.67M ³
					Total Qty = 72.97M ³
② Maintenance of Earthen Shoulders					
	3X	8.00X	2.25 =		54.00M ²
	3X	9.00X	2.20 =		59.40M ²
	4X	5.50X	1.95 =		42.90M ²
	3X	7.75X	1.90 =		21.38M ²
	6X	3.50X	2.25 =		47.25M ²
	2X	6.00X	1.95 =		22.80M ²
	4X	6.20X	2.20 =		54.50M ²
	4X	7.20X	2.30 =		66.24M ²
	4X	3.20X	2.30 =		29.44M ²
					Total Qty = 387.91
③ Maintenance of H.P Culverts - 3 NOS					

Continuation

N/W - Dahari Rawat ke
ghar to Ramnath
tiwari ke ghar tak -

N/A - Maa Jagdamba Construction
Aat PO - Khampur Manghi-Saran

Agb No - 13 SBD / 2018 / 019
Date of Start - 16/01/019
Date of Completion - 15/10/019
Date of Actual Completion -
Date of Entry -

Measurement and abstract
have been mentioned in
the previous Page.

Scanned with CamScanner