

5th year maintenance

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	

N/w: L24 Chokhab to Hangan

10/9 work ab 11-19k.

Agency - Sri. Vishwanathan Kumar

Ag. No. - 13 (SRD) / 2017-18

D.O.W - 05.07.2017

A.D.O. - 05.08.2020

① Restoration of Rain Cuts -

$$24 \times 2.65 \times 0.75 \times 0.30 = 14.91$$

$$28 \times 2.50 \times 0.85 \times 0.30 = 17.85$$

$$31 \times 2.60 \times 0.70 \times 0.35 = 19.75$$

$$26 \times 2.15 \times 0.60 \times 0.30 = 11.93$$

$$25 \times 2.15 \times 0.90 \times 0.30 = 14.57$$

$$26 \times 2.10 \times 0.85 \times 0.35 = 13.92$$

92.27 m³

limt. - 92.04 m³

② Maintenance of Earthen
Shoulder -

$$20 \times 5.00 \times 0.60 = 60.00$$

$$20 \times 4.00 \times 0.85 = 68.00$$

$$25 \times 5.00 \times 0.90 = 112.50$$

$$24 \times 5.00 \times 0.85 = 102.00$$

$$15 \times 5.00 \times 0.80 = 60.00$$

$$12 \times 7.00 \times 0.70 = 58.80$$

$$20 \times 5.00 \times 0.50 = 50.00$$

571.30 m²

③ Maintenance of Road
Sign -

1.010 km

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
1386.0 m ² @ 2.01 / m ²					2786 =
				E.	63166 =
Less 10% Allowance				G. H.	6317 =
				I.	56849 :
<u>masonry</u>					
C/W - 168.74 m ³					