

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
H/Walk - Maintenance of Road					
from HH-104 (Ranipatti)					
to Raghunathpur.					
Agcy - Sri Arvind Thakur					
Ag. No -	10-5137/19-20				
D/Start -	11/01/20				
Act. Gubli -	28/5/22				

Measurements				
(1) Pr. Restoration of Rain-cuts.				
as per Specifica -				
3	x	27.0m	x	1.30 x 0.300 = 31.60m ³
2	x	18.0m	x	1.10 x 0.300 = 11.88m ³
1	x	22.50m	x	1.35 x 0.300 = 9.11 "
5	x	2 x 10.0m	x	0.50 x 0.300 = 15.0m ³
3	x	13.0m	x	0.90 x 0.300 = 10.50m ³
7	x	12.0m	x	0.70 x 0.300 = 17.64m ³
5	x	20.0m	x	0.60 x 0.300 = 18.0m ³
12	x	2 x 3.0m	x	0.90 x 0.300 = 19.44m ³
Total =				133.17m ³
(2) Maintenance of Earthen				
Shoulders as per Specifica -				

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
<u>Abstract of Cost:</u>					
(1) Repair. of Rain cuts.					
vide Item-1, P-73					
= 133.17 m ³					
@ Rs 379.59/m ³ - Rs 50550 =					
(2) Maint. of Shoulders					
vide Item-2, P-74					
= 697.98 m ³					
@ Rs 56.81/m ³ - Rs 39652 =					
(3) Plc - 75 mm. B.M.					
vide Item-3, P-74 = 6.90 m ³					
@ Rs 10539.06/m ³ - Rs 72720 =					
(4) Patch Repair - Pot holes					
vide Item-4, P-74 = 91.88 m ³					
@ Rs 251.03/m ³ - Rs 23065 =					
(5) Maint. of H/P Culverts					
vide Item-5, P-75 = 0.3 Km.					
@ Rs 1102.80/km - Rs 3308 =					
(6) Maint. of Road signs					
vide Item-6, P-75 = 0.290 Km.					
@ Rs 1054.28/Km - Rs 302 =					
(7) Maint. of Km Shant					

Continuation

Continuation