

4th Year Maintenance

Sch. XLV-Form No.134. 19

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work- Maintenance of road from Phenhar road to Birta Tal under MINSY Agency- Vijay Kumar Singh Agreement No- 69 SBD/2018-19 Actual date of Completion- 20/01/2020 4 th Year Maintenance? 2-11/01/2023 to 20/01/2024 Period					
① Restoration of Rain cuts					
2 X 7.10 X 0.90 X 0.30 =					3.8311
3 X 10.10 X 1.15 X 0.25 =					8.6211
3 X 7.10 X 1.15 X 0.25 =					6.0311
2 X 9.50 X 1.10 X 0.25 =					5.2211
3 X 10.10 X 1.25 X 0.30 =					11.2511
2 X 6.10 X 1.25 X 0.30 =					4.5011
3 X 8.50 X 1.15 X 0.30 =					8.8011
2 X 11.50 X 1.25 X 0.25 =					7.1911
2 X 10.50 X 1.28 X 0.25 =					6.7211
2 X 6.10 X 1.25 X 0.30 =					4.5011
3 X 11.10 X 1.10 X 0.25 =					9.0711
4 X 8.50 X 1.20 X 0.30 =					12.2411
2 X 6.15 X 1.20 X 0.25 =					3.6911
1 X 7.60 X 1.20 X 0.30 =					2.7411
1 X 6.15 X 0.90 X 0.30 =					1.6611
1 X 6.50 X 0.90 X 0.30 =					1.7511
1 X 10.60 X 1.20 X 0.25 =					3.1811
					100.9911

Continuation

Abstract of cost

Sch. XLV-Form No.134

22

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
① Restoration of Rain cuts					
Q-VTNB/19① = 100.99 m					
e h 3.65 m / h R - 36.887 = 0					
② Maintenance of earthen shoulder					
Q-VTNB/20② = 311.30 m					
e h 54.37 m / h R - 16925 = 0					
③ Maintenance of bituminous surface road					
(i) Repair to Pot holes					
Q-VTNB/20③ = 67.80 m					
e h 294 = 281 m / h R - 19952 = 0					
Q-VTNB/20③ = 67.80 m					
e h 415 = 96 m / h R - 28202 = 0					
(ii) Patch repair					
Q-VTNB/20③ = 67.80 m					
e h 278.50 m / h R - 18882 = 0					
④ Maintenance of H.P. culvert					
Q-VTNB/21④ = 1 NA					
e h 1131 = 64 / each R - 1132 = 0					
⑤ White washing of lamp post					
Q-VTNB/21⑤ = 24.47 m					
e h 16.80 m / h R - 411 = 0					
⑥ cutting of branches of trees					
Q-VTNB/21⑥ = 8 NA					
e h 107 = 48 / each R - 860 = 0					

Continuation

