

3rd year Maintenance

66

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
N/W - Maintenance of road					
from Ward No-8					
Dandi Mamlal					
house to Sah					
tola JRC-Nahar					
61 RD					
Agency - Priyashu Constr					
Agg No - 38 SRD / 21-22					
Date of Commencement					
18/06/21					
Date of Completion					
17/03/22					

①	Restoration of				
	Rain Cut -				
	10 X 3.50 X 2.50 X 0.30 = 26.25				
	8 X 3.80 X 2.10 X 0.30 = 19.15				
	02 X 3.00 X 2.50 X 0.30 = 4.50				
	5 X 3.00 X 2.00 X 0.30 = 9.00				
	2 X 2.00 X 1.50 X 0.30 = 1.80				
	Total = 60.70 m ³				
②	Making up of				
	berms / Shoulder				
	18 X 1.50 X 1.20 = 32.40				
	10 X 4.50 X 1.00 = 45.00				
	16 X 3.50 X 1.00 = 56.00				
	12 X 3.00 X 1.00 = 36.00				
	8 X 4.00 X 1.00 = 32.00				

Continuation

Abstract of Cost

69

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(1) Restoration of Rein. Curt					
60.70 m ³ Qty TMBP-66					
@ 380.58 / m ³					
R _a ——— = 23101.10					
(2) Making up Berms / Shoulder					
290.12 m ² Qty TMBP-67					
@ 58.60 / m ²					
R _a ——— = 17001.10					
(3) Repair to pot holes filled					
3.22 m ³ Qty TMBP-67					
@ 12103.28 / m ³					
R _a ——— = 38973.10					
(4) Patch & repair over pot holes with Mix Seal-					
42.82 m ² Qty TMBP-67					
@ 261.33 / m ²					
R _a ——— = 11216.10					
(5) Patch & repair over bituminous Surface					
42.82 m ² Qty TMBP-67					
@ 261.93 / m ²					
R _a ——— = 11216.10					
(6) Maintenance of C/P work					

Continuation

Continuation