

To S
path tak
hereinat
contract
shwar
of the

4th year maintenance

63

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
N/w: Komtishanpur REO Sadak to					
Bishanpur REO.					
Agency - Hq. Mutaba.					
Ag. No - 04(337) 2019-20					
D.O.W - 21.09.2019					
Actual D.O.C - 02.09.2020					
① Restoration of Rain Cut -					
15 x 3.10 x 1.10 x 0.30 =					15.34
12 x 2.80 x 0.95 x 0.35 =					11.17
20 x 3.25 x 1.15 x 0.35 =					26.16
16 x 2.5 x 1.20 x 0.35 =					17.14
24 x 3.10 x 1.00 x 0.30 =					22.32
12 x 2.40 x 0.90 x 0.35 =					9.07
					1
					101.20 m ³
② Paint. of Beams/shoulder -					
25 x 5.00 x 0.90 =					112.50
17 x 7.50 x 0.85 =					108.37
20 x 6.70 x 0.90 =					120.60
15 x 10.00 x 0.80 =					120.00
22 x 8.00 x 0.95 =					167.20
24 x 5.00 x 0.80 =					96.00
					724.67
③ Repair to pot holes with					
WBM					
14 x 2.65 x 1.00 =					37.10
12 x 2.95 x 1.10 =					38.94
10 x 2.40 x 0.90 =					21.60
					97.64 m ²

Continuation

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	

S. w. N. @ R 1117.00 / met K 9357 =

R. 140509 =

Len 10 ft. Below — to R 14051 =

R 126458 =

Sum
09/9-21
10

Material

c/w - 205.20 m³

s/mul - 10.24 m³

s/cush - 3.037 m³

R-1 - 33.75 kg

Bitumen - 0.240 MT

Sum
02/9-21
02