

MM: 15/10/2011
SH
2011-12/10/2011

Schedule XLV-Form No. 134

2011-12

DIVISION

SUB-DIVISION

2011-12

Measurement Book

5th year Maintenance Bill

95

ch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work	5 th year maint. work of				
	Kunjra-tala to Ram-tala				
Agency	Mumtaz Alam, Mathura, Ward no- 6 (Harpatganj)				
Aggr. no	49/SBD/2018-19				
Date of start	10-09-2018				
Date of completion	09-06-2019				
Actual date of completion	20-01-2020				
(1) Restoration of rain cuts with Sall. as per T/S					
6 X 2.70m X 1.00m X 0.30m					4.86 m ³
8 X 3.20m X 1.10m X 0.30m					8.45 m ³
3 X 30.0m X 1.00m X 0.30m					27.00 m ³
7 X 30.0m X 1.00m X 0.30m					63.00 m ³
6 X 30.00m X 1.0m X 0.30m					54.00 m ³
1 X 28.0m X 1.0m X 0.30m					8.40 m ³
1 X 18.30m X 1.0m X 0.30m					5.49 m ³
1 X 14.80m X 1.0m X 0.30m					4.44 m ³
1 X 22.60m X 1.0m X 0.30m					6.78 m ³
1 X 26.28m X 1.0m X 0.30m					7.90 m ³
1 X 12.60m X 1.0m X 0.30m					4.56 m ³
1 X 30.0m X 1.0m X 0.30m					9.00 m ³
1 X 23.20m X 1.0m X 0.30m					6.96 m ³
Total					213.84 m³
(2) Making up dose of material / irregularities on shoulders to the design level by adding as per T/S					
2 X 30.0m X 1.10m					66.00 m ²
8 X 30.0m X 1.00m					240.00 m ²
6 X 30.0m X 1.10m					198.00 m ²
Continuation					

Continuation

Materials Statement

E/12 ————— = 2 13.84m³

Stone masonry Gr-III 135.85m³

Bitumen 5-99 = 0.021m³

[Signature]
06/3/15
DE