

3rd year maintenance.

42

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
N/Work:- Main ⁿ of Road from					
Muraepur to Ishandri					
Maharaja Middle School.					
N/Agency:- Randhir Kumar					
Agg. No:- 335 S.B.D/2021-22					
D.O.S:-	27.	07.	2021		
A.D.D.C:-	22.	06.	2022		
Date of measurement.					
(1)	Restoration of rain				
	cuts - do - do - E/I				
	7x	9.00x	0.70x	0.30	13.23m ³
	9x	8.00x	0.60x	0.30	12.96m ³
	8x	8.00x	0.80x	0.30	15.36m ³
	7x	9.00x	0.90x	0.30	17.01m ³
	8x	8.00x	0.80x	0.30	15.36m ³
	9x	11.00x	0.80x	0.30	23.76m ³
	13x	12.00x	1.20x	0.30	56.16m ³
				Qty=	153.84m ³
(2)	Main ⁿ of earthen				
	Shoulder - do - do - E/I				
	11x	11.00x	0.80	=	96.80m ²
	13x	9.00x	0.70	=	81.90m ²
	12x	13.00x	0.60	=	93.60m ²
	14x	11.00x	0.80	=	123.20m ²
	13x	12.00x	0.70	=	109.20m ²
				Qty=	504.70m ²

$\chi^2 = 2.08$ d.f. = 1

[illegible]