

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
M/w. Maintenance of Road from Agun thakur ke gram (wastinagar) to Bairagarh Bahadur talu.					
Agency -	Rastu Bagan				
Agreement -	18 (SBD) / 2020 - 21				
D.O.W -	10.08.2020				
A.D.O.C -	02.08.2021				

① Restoration of Raincut

$$18 \times 2.25 \times 0.70 \times 0.35 = 9.92$$

$$21 \times 2.30 \times 0.95 \times 0.35 = 16.06$$

$$16 \times 1.75 \times 0.80 \times 0.35 = 7.84$$

$$12 \times 2.15 \times 0.85 \times 0.35 = 7.68$$

$$15 \times 1.95 \times 0.90 \times 0.30 = 7.90$$

$$14 \times 2.20 \times 0.90 \times 0.30 = 8.32$$

$$11 \times 2.10 \times 0.75 \times 0.35 = 6.06$$

$$26 \times 1.85 \times 0.85 \times 0.30 = 12.27$$

$$24 \times 2.00 \times 0.75 \times 0.35 = 12.60$$

$$20 \times 1.95 \times 0.80 \times 0.30 = 9.36$$

$$98.01 \text{ m}^3$$

② Maintenance of Earthen

shoulder

$$25 \times 5.00 \times 0.75 = 93.75$$

$$30 \times 5.00 \times 0.80 = 120.00$$

$$27 \times 5.00 \times 0.70 = 94.50$$

$$32 \times 5.00 \times 0.75 = 120.00$$

$$24 \times 5.00 \times 0.80 = 96.00$$

$$524.25 \text{ m}^2$$

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(5) Patch repair on already filled hole					
Qty wire mesh (34)					
25.85					
25.15 m ² @ 248.14/m ²					6414:
(6) Maint. of Road sign -					
Qty wire mesh (34)					
1.115 km @ 1054.28/km					1176:
(7) Maint. of 200 m of boundary -					
Qty wire mesh (34)					
0.19 km @ 688.36/km					131:
(8) Cutting of Branches -					
Qty wire mesh (34)					

7.00 Nos @ 106.12/each					743:
(9) Trimming of boundary					
Qty wire mesh (35)					
945.00 m ² @ 217/m ²					2051:
					89906:
Acryl coat + L. cell (134) (4) B					11688:
					101594:
Less Below soil					10159:
					91435:
<u>Summarized</u> <u>29/08/25</u> <u>J.E</u>					