

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
<u>ON 5-1/2 year maintenance bill :-</u>					
<u>Name of Work :- Maintenance of Road</u>					
<u>from PMSY Road to Annulha</u>					
<u>Road No. Bahadur Tak, Via 11.</u>					
<u>Bareilly Road Khat. to Mubayda</u>					
<u>Road Ghat. Hata Hill.</u>					
<u>Name of Agency :- M/s DEVEDRA</u>					
<u>Kumar & Company, Muzpur</u>					
<u>Agg NO :- 785 SBT/2018-19</u>					
<u>D.O.S :- 18/12/2018</u>					
<u>D.O.C :- 17/12/2019</u>					
<u>A.D.O.C :- 14/09/2019</u>					

<u>Date of measurement</u>					
<u>1) Restoration of rain cuts :-</u>					
17	4.3	1.2	0.3	=	26.316 m ³
15	4.1	1.1	0.3	=	20.295 m ³
14	4.2	1.2	0.3	=	21.168 m ³
19	4.6	1.1	0.3	=	28.842 m ³
18	4	1	0.3	=	21.6 m ³
16	4.9	0.9	0.3	=	21.165 m ³
<u>Total qty. =</u>					<u>139.389 m³</u>
<u>2) Maintenance of pavilion shoulder :-</u>					
15	4.9	x	0.95	=	69.825 m ²
16	4.5	x	1	=	72 m ²
18	5	x	0.8	=	72 m ²
15	4.9	x	0.9	=	66.15 m ²
16	4.1	x	1.1	=	72.16 m ²

Continuation

