

प्राप्ति किता 5727 है कि 58 मापी यतिनका
 प्रि. 1010 एक (1) 713 डेकिर है

55

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
5th year maintenance Bill					
N/W - Const- to Road from					
Chaknathan Bishunpur					
Pathank SE Chaknathan					
Pokhar via Bhatoliya					
Agency:- Asit Kumar					
Ag. No - 81 SBD/18-19					
Date of work order - 18.12.2018					
Date of Completion - 08.06.20					
① Restoration of rain					
Cuts and berms.					
$12 \times 8.68 \times .88 \times .30 =$					27.50 m ³
$14 \times 7.55 \times .85 \times .30 =$					26.85
$12 \times 7.25 \times .85 \times .30 =$					22.18
$9 \times 10.75 \times .90 \times .30 =$					26.12
$11 \times 10.25 \times .85 \times .30 =$					28.75
$8 \times 6.55 \times .75 \times .30 =$					15.61
$12 \times 7.85 \times .70 \times .30 =$					25.43
$4 \times 6.8 \times .80 \times .30 =$					6.24
					163.17 m ³
				Lt.	161.02 m ³
2. making up berms					



Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
4. Patch repair on all ready filled pot hole - do E/B					
107.48 m ² V.P- 56					
@ 208.80/m ² - R					22442.0
5. Maint - do H.P Culvert					
05 Nos V.P- 56					
@ 1131.64/Each - R					5658.0
6. Maintenance of road slabs					
1.7671 km V.P- 56					
@ 1087.63/km - R					1922.0
7. maintenance of 200mm and 150mm foot					
0.424/km V.P- 57					
@ 738.55/km - R					313.0
8. Cutting branches of tree					
11 Nos V.P- 57					
@ 107.48/Each - R					1182.0
C.O.B.					175364.0
Recd 04.05.25 J.E					
04.05.25 H					