

2 62

Schedule XLV-FORM No-134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
		5th year	Maintenance	Bidi	
N/W-		Const. of Road	From		
		Dewariya Bherha	Tola		
		Ramishis	Postman	house	
		to	Baliga	East	
		Prathmic	School		

Agency:- Shyam Kumar

Ag. No - 605ADJ 2018-19

Date of work order - 19.11.2018

Actual date of Completion:- 12.12.2019

① Restoration of drain
cuts and berms
do. E/g

$$7 \times 9.30 \times .95 \times .30 = 18.55 \text{ m}^3$$

$$5 \times 12.10 \times .80 \times .30 = 14.52$$

$$4 \times 8.5 \times .90 \times .30 = 9.18 \text{ m}^3$$

$$6 \times 5.50 \times .75 \times .30 = 15.94$$

$$8 \times 10.5 \times .90 \times .30 = 22.68$$

$$7 \times 6.5 \times .80 \times .30 = 10.92$$

$$4 \times 7.5 \times .80 \times .30 = 7.20$$

$$\text{C.O. Qty} = 88.95 \text{ m}^3$$

$$\text{Lt.} = 85.29 \text{ m}^3$$

2.17 making up berms
and shoulder do
do. E/g

$$6 \times 15.25 \times .90 = 82.34 \text{ m}^2$$

$$9 \times 7.5 \times .90 = 60.75$$

$$12 \times 9.25 \times .95 = 105.45$$

$$6 \times 11.25 \times .90 = 60.75$$

$$8 \times 9.85 \times .85 = 65.62$$

$$11 \times 9.85 \times .95 = 102.93$$

$$6 \times 3.2 \times .80 = 15.36$$

$$\text{C.O. Qty} = 493.20 \text{ m}^2$$

$$\text{Lt.} = 473.55 \text{ m}^2$$

Continuation



