

50/50 Year

Babhane Tola Babhiga

Schedule XLV-Form No. 134

Page id - PT 355062

To Log Under MINGSY (SS)

F. F. R. W. D. (W)

DIVISION
6749A

A. F. R. W. D. (W)

SUB-DIVISION
1142IR1141N5

P. 6000 Koma

MEASUREMENT BOOK

30085

Particulars	Details of actual measurement			Contents of area
	No.	L.	B.	
Name of work - const of road				
From Babhami				
Barbigha - talu Barbigha Talu				
under ministry				
Agency - panam Kumar				
Agtd No - 132/mm/57/50/SB/2029-22				
DOW - 20.05.21				
TOL - 19.02.22				
(1) Restoration of (rim)				
cuts / Berms with soil.				
30.07 m ²				
(2) making up of Berms				
shoulder				
167.06 m ²				
(3) Repair of pot holes				
filled with 75 mm				
HBM x 1.25				
0.07 m ²				
(4) patch repair over				
potholes with 20 mm				
premix carpet and				
seal coat				
23.20 m ²				

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(5) patch repair over bituminous surface with 20mm mix seal surfacing					
					23.2 m ²
(6) cracksealing - filling of cracks and joints excluding					
					495 m
(7) Repair of isolated areas of damaged concrete pavement					
					12.42 m ²
(8) Removal of existing sealant and resealing at construction					
					248.44 m
(9) maintenance of c/d works (Hume pipe culvert)					
					2.00 NO
(10) maintenance of c/d works (slab culvert)					
					1.00 NO

Continuation

R.P. 11/12/20

कार्यपालक अभियंता

प्राचीन कार्य विभाग

सुरक्षा समिति

Quantities
of area

Particulars	Details of actual		Quantities of area
	No.	L.	
(10) maintenance of road signs		0.76 km	
(11) maintenance of 200 m and km stone		0.76 km	
(12) cutting of branches of trees and shrubs		5.00 No	
(13) cutting of shrubs from roadway		495 No	
(14) Trimming of grass and weeds		1114 m ²	
(15) White washing of parapet walls of C work and tree trunks		63.00 m ²	
1.000 2.000 1.0			

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Abstract of cost.					
(1) Restoration of Rainwater Berm					
		30.07 m ²			
@	404 ± 06			Rs = 12150 = 08	
(2) making up of Berm shoulder					
		167.06 m ²			
@	60 ± 28			Rs = 10070 = 00	
(3) Repair of pot holes filled with 75 mm WBM x 125					
		0.07 m ²			
@	9325 ± 58			Rs = 653 ± 00	
(4) patch repair over potholes with 20 mm premix carpet and seal coat					
		23.02			
@	243 ± 82			Rs = 5657 ± 00	
(5) patch repair over bituminous surface with 20 mm mix seal surfacing					
		23.02 m ²			
@	261 ± 24			Rs = 6061 ± 00	

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(12) maintenance of 200m and Km stones					
		0.71 Km			
(a)	643=17			Rs= 489=00	
(13) cutting of branches of trees and shrubs					
	5.00 No				
(a)	113=64			Rs= 568=00	
(14) cutting of shrubs from roadway					
	495 No				
(a)	6=98			Rs= 345.5=00	
(15) trimming of grass and weeds					
	1114.17				
(a)	2=33			Rs= 2596=00	
(16) White Washing of parapet walls of c/s work and tree trunk					
	68000 m ²				
(a)	16=80			Rs= 1058=00	
				Rs= 59953=00	
Balance 00.00				Rs= 308=00	
				Rs= 58945=00	