

MM5151-NDB

Schedule XLY-Form No. 134

PM Guy Road to Hudson Tola

Agony for each known farm

~~1907-56~~

DIVISION

~~1907-56~~

SUB-DIVISION

MEASUREMENT BOOK

1st year maintenance work,

Record Entry

N/A: First year maintenance.

for P. MURSY Road

to Mushan to 19

N/A: Sachin Kamargum

DIS: 31.01.2023

D/Completion: 30.01.2024

Sr no ① SOR NO - 15.15 -

Item no

Restoration of Ram.

Cuts / Berms with.

Soil masonry etc.

2x10 x 0.500 x 0.300 - 3.00

3x10 x 0.600 x 0.300 - 5.40

2x15 x 0.650 x 0.300 - 5.85

Continuation

Beh. XLV Form No. 134

Particulars	Details of actual measure				Contents of area
	No.	L	B	D	
sr. no (1)	SOR 15.12 (1)				
	cutting of branches of tree and shrubs				
			Qty		02 nos
sr. no (5)	SOR 15.13 :-				
	House & white washing of parapet wall of C.D. work and tree trunks -				
	2 x 2 x 6	150	0.400		9.84
	2 x 4 x 6	150	0.600		29.52
	2 x 4 x 0.400		0.600		1.92
			Qty		41.28 m ²

22/03/2025
J.E

Nile P
22/3/25
SR

Abstract of cost.

sr. no (1) SOR 15.1 :- Restoration.

of Rein culs / Berm.

with Soil masonry etc.

vide T.M.B, Page no-42

Qty 31.35 m³ @ ₹ 404.06/m³

12667 = ∞

sr. no (2) SOR 15.2 :- Making

up Berm / Shoulder

Stripping excess soil

Continuation

C.O - 12667 :- 4

Sch. XLV-Form No. 134

Particulars	Details of actual measure				Contents of area
	No.	L.	B.	D.	
			B. E	— 2	30,148.24
Less 0.18% Bellm				(-) 2	54.20
Amount				2	30,144.20

22/08/2025
J.E

Nik
22/8/25
N.E

Material Statement.

Sol — $176.25 \times 0.275 = 48.46875$

5-Expanded
M.D (M) DIVISION
EXECUTIVE ENGINEER