

75(1-1137) H. 09/503 of 20-21

204124 41127 471154 - 91.5.20
Chm 471154 - 10.2.21

10.2.24

07/11/2017

Ms. B. 1. 10

2nd year maintenance

38

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
M/N:- Maint. of road 120m					
Belawan PHDSY to Belawan pagchim 119.					
M/P:- SRI- Ritesh K. Pari.					
A/N:- 09 SBD / 2020-2021					
Date of actual completion:- 25.3.2022					
Date of Measurement:-					
Details of work:-					
Item No (1):- Restoration of					
rain cuts with soil					
4 x 30-00 x 0-75 x 0-30					27.00m ³
Item No (2):- Making up of					
road from 110m to 120m					
06 x 30-00 x 0-80					144.00m ²
01 x 7-50 x 0-80					6.00m ²
					150.00m ²
Item No (3):- Repair of Pot					
holes with H.S.S					
20 x 1-50 x 0-50					15.00m ²
02 x 2-50 x 0-30					1.50m ²
03 x 1-20 x 1-00					3.60m ²
					20.10m ²
Item No (4):- Maint. of H.P					
valves etc					0.2 Nos
Item No (5):- Maint. of road					
signs					0.05 Nos

Continuation



Continuation