

2nd Year Maintenance

47

Sch. XLV—Form No. 134

Sch. XLV—Form No. 134					
Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
N/w- Maint. of Road from					
Bahuarua To Shapsi Paha.					
Agency- M/s vijay kumar Tiwari					
Ag. No- 20560/2022-2023					
Date of start - 01/09/2022					
Actual completion- 31/08/2023					

Record by

① Restoration of rain
cuts → 20 →

12 x 4.40 x 1.00 x 0.80 =	15.84
16 x 2.90 x 1.10 x 0.80 =	20.89
9 x 4.60 x 1.05 x 0.80 =	12.04
8 x 4.90 x 0.95 x 0.80 =	11.17
7 x 5.20 x 0.90 x 0.80 =	10.02
6 x 6.40 x 0.85 x 0.80 =	9.79
8 x 5.20 x 0.80 x 0.80 =	10.18
9 x 5.10 x 1.125 x 0.80 =	15.49
8 x 5.57 x 0.75 x 0.80 =	10.02
	116.15 m ³

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
R/F —	6				972617.00
Add GST @ 12% —	6				82714.00
Add 2.C @ 1% —	6				9726.00
Add S.Fee —	6				915.00
Total:	6				808972.00
less @ 0.01% Ref new —	6				81.00
Total:	6				808941.00
<i>Agreed</i> 20/09/25 J.S. <i>Agreed</i> 20/09/25 A.C. <i>Agreed</i> 20/09/25 T.S.					
Material used:-					
Earthwork —					292.586 m ³
Emulsion —					29.00 k
Bitumen —					192.00 k
Stone Chips —					2.420 m ³
Sand —					0.588 m ³
<i>Agreed</i> 20/09/25 J.S. <i>Agreed</i> 20/09/25 T.S.					