

**Format for Inspection of Maintenance Aspects of completed works by  
PIU Vide Lt- 1064, Date- 11-12-2018 of Secretary, RWD, Patna**

1. Date of Inspection:
2. Name of PIU:
3. State: BIHAR District: N. CHAMPARN Block: THAKRAHA
4. Name of Road: From Malahighat Dhumnaga to Belwari Patti
5. Package No.: BR-37R-545
6. Year of clearance: 00-01 Ph-1 01-03 Ph-2 03-04 Ph-3 04-05 Ph-4 05-06 Ph-5
7. Length: Flexible Pavement ....Km CC/other Pavement .....Km.  
= Total 1:61....Km.
8. Estimated Cost (As cleared by GOI): Rs. 130.28 Lakh
9. Cost upon Completion: Rs. 126.23 Lakh
10. The Work is a Case of: ☒ New connectivity ☐ Up gradation
11. Actual Date of Completion: 20 05 17

**Observations:**

<b>1</b>	<b>Name of Item/ Activity:</b> Maintenance of road in respect to Restoration of rain cuts as per clause 1902 of the Specifications and Cutting of branches of trees, shrubs and trimming of grass and weeds etc as per clause 1914 of the Specifications.	
<b>a</b>	<b>Observations:</b> What is the condition of Roads in respect to this item: <div style="border: 1px solid black; padding: 10px; margin-top: 10px;">                     Flanres Restored and shrubs are not over the Carriage way                 </div>	
<b>b</b>	Grading for the above item	S / U     151
<b>2</b>	<b>Name of Item/ Activity :</b> Restoration of rain cuts and dressing of berms as per clause 1902 of the Specifications and making up of shoulders as per clause 1903 of the Specifications	
<b>a</b>	<b>Observations:</b> What is the condition of Roads in respect to this item : <div style="border: 1px solid black; padding: 10px; margin-top: 10px;">                     Shoulder is maintained Restored in Rain Cuts.                 </div>	
<b>b</b>	Grading for the above item	S / U     151

3	<b>Condition of Pavement including filling pot holes and patch repairs etc as per clause 1904, 1905 and 1906 of the Specifications.</b>				
a	<b>Observations:</b> What is the condition of Roads in respect to this item (Detailed observations should be made as to whether the pavement has potholes, cracking, reveling etc which is causing disturbance/discomfort in driving ? if yes, whether these defects have been repaired properly under routine maintenance:  B.T. Surface is in good Condition no - Pot holes as well as P.C.C. Portion is maintained				
b	<b>Observations:</b> What is the pavement condition index (PCI) as per annexure 14.7 para 14.9 of Operations manual?	5	4 ✓	3	<3
c	Grading for the above item	S / U			
4	<b>Name of Item/ Activity :</b> Maintenance of drains as per clause 1907 of the Specifications, Maintenance of culverts and cause ways as per clause 1908 and 1909 of the Specifications				
a	<b>Observations:</b> What is the condition of Roads in respect to this item :  Road is cross through Habitude Area from PWD to end of village. So No any Culvert available.  N/A				
b	Grading for the above item	S / U			

5	<b>Name of Item/ Activity :</b> Maintenance of road signs as per clause 1910 of the Specifications and White washing guard stones, Re-fixing displaced guard stones, White washing parapets of C.D. Works	
a	<b>Observations:</b> What is the condition of Roads in respect to this item :  K.M. post Road signage Painted Maintenance Booked and also P.M.U.M.	
b	Grading for the above item	S / U 151
6	<b>Name of Item/ Activity:</b> Maintenance of guard rails and parapet rails as per clause 1911 of the Specifications, Maintenance of 200 m and Kilo Meter stones as per clause 1912 of the Specifications.	
a	<b>Observations:</b> What is the condition of Roads in respect to this item :  K.M. Post are placed but 200 M not placed. Required improved.	
b	Grading for the above item	S / U 101
7	<b>Over all grading</b>	S/ SRI/ U 3 R 5

  
 13/12/2018  
 Signature

Name of PIU

Date: