MMGS7 (Gen)

Format for Inspection of Ivaintegance Aspects of completed PMGSY Work				
1. Date of Inspection: 12/12/18				
2. Name of National Quality Monitor				
3. State: Bihar District: East Champaran Block: Chalcia				
4. Name of Road: From Sita kundio Chintaman puz Brahm Asthan Barwa				
5. Package No: MMC17 (Gen)				
6. Year of clearance: 00-01Ph-1 01-03 Ph-2 03-04 Ph-3 04-05 Ph-4 05-06 Ph-5				
7. Length in Flexible pavement 046 CC/other pavement -0.60 Km. Total- 1.057 Km.				
8. Estimated Cost (As cleared by GOI): 84.86804				
9. Cost upon Completion: 84.86804 82.08489				
10. The Work is a Case of: New connectivity Up gradation				
Observations:				
Name of Item/ Activity: Maintenance of road in respect to Restoration of rain cuts as per clause 1902 of the Specifications and Cutting of branches of traps starebs and tranming of grass and wends are as per clause 1914 of the Specifications.				
a Observations: What is the condition of Roads in the respect of this item.				
Cutting of branches of tree & shoulder				
has been done Satisfactory.				
b Grading for the above item S/U				
Name of Item/ Activity: Restoration of rain cuts and dressing of beams as per clause 1902 of the Specifications and making up of shoulders as per Claus (707) of the Specifications.				
Restoration of roun Corts has been				

3	Condition of Pavement including filling pot holes and patch repairs etc as per clause 1904, 1905 and 1906 of the Specifications.			
a	Observations: What is the condition of Read in account to the in (Davillet) about			
	Observations: What is the condition of Road in respect to this item (Detailed) observations			
-	should be made as to whether the pavement has potholes, cracking reveling etc which is			
	causing disturbance/discomfort in driving? if yes, these defects been remained properly			
	routing maintenance			
	Condition of parement has been found Saturfactory. No any distant			
	found Satisfactory. No any distant			
	in Driving rechiles.			
b	Observations: What is the pavement condition index 5 4 3			
	(PCI) as per annexure 14.7 Para 14.9 of Operations			
	manual?			
С	Grading for the above item S/U			
	Stating for the above facility			
4	Name of item/ Activity: Maintenance of drains as per clause 1907 of the Specification,			
	Maintenance of culverts and cause ways to per clause 1908 and 1909 of the Specifications			
2	Observations: What is the condition of Road in respect to this item:			
	and of the area of and Constitution.			
	Culvesto are in good Condition.			
•				
b	Grading for the above item S/U-			
-				

5	Name of Item/ Activity: Maintenance of Road signs us per clause 1910 of the Specification			
	are white washing guard stones Re-fixing displaced Guard stones, white washing			
	parapet's of C.D. works			
		N. 13		
a	Observation: What is the condition of Road in respect to this item:	Siz .		
		2 200		
		1.1-		
	Road Signs are Maintained Satisfactory			
	The same of the sa			
		3.5 m		
Ъ	Grading for the above item S	/U		
0	Grading for the above item	70		
6	Name of Item/ Activity: Maintenance of guard rails and parapet rails as per	clause 1911 of		
	the Specifications, Maintenance of 200 m and Kilo Meter stones as per			
	the Specifications.			
	are operitorial.			
-	Observations What is the condition of Road in respect to this item			
a	Observation: What is the condition of Road in respect to this item:	u		
	Che host looks hout no foreme			
	post post source posts are plante			
	Kny fost 200 m fosts are foured Satisfactory			
-	Satisfactory			
,				
	10 . 40			
	of Salika			
	V			
ь	Grading for the above item	S/U		
7	Over all grading	S/SRI/ U Satisfacting		
E				

Date:

Signature Signature Raw Raw