

Format for Inspection of Maintenance Aspects of completed PMGSY works by Second Tier of SQM/PIU

1. Date of Inspection: 13-12-2018
2. Name of State Quality Monitor/PIU: Arshad Alam
3. State: Bihar District: Jamui Block: Jhajha
4. Name of Road: From Sahia main road - Chandrapura.
5. Package No.: BR-15R-103
6. Year of clearance 2011-12
7. Length: Flexible Pavement 1.484 Km CC/other Pavement 0.100 Km. = Total 1.584 Km.
8. Estimated Cost (As cleared by GOI): Rs. 81.66 Lakh
9. Cost upon Completion: Rs. 76.31 Lakh
10. The Work is a Case of: New connectivity Up gradation
11. Actual Date of Completion: 25 03 16

Observations:

1	Name of Item/ Activity:	Maintenance of road in respect to Restoration of rain cuts as per clause 1902 of the Specifications and Cutting of branches of trees, shrubs and trimming of grass and weeds etc as per clause 1914 of the Specifications.
a	Observations: What is the condition of Roads in respect to this item:	Rain Cuts restored. Branches of trees in road cut. Trimming of grass & weeds done
b	Grading for the above item	✓ S/U 'S'
2	Name of Item/ Activity :	Restoration of rain cuts and dressing of berms as per clause 1902 of the Specifications and making up of shoulders as per clause 1903 of the Specifications
a	Observations: What is the condition of Roads in respect to this item :	Restoration of rain cuts and dressing of berms done
b	Grading for the above item	✓ S/U 'S'

3	Condition of Pavement including filling pot holes and patch repairs etc as per clause 1904, 1905 and 1906 of the Specifications.				
a	<p>Observations: What is the condition of Roads in respect to this item (Detailed observations should be made as to whether the pavement has potholes, cracking, releveling etc which is causing disturbance/discomfort in driving ? if yes, whether these defects have been repaired properly under routine maintenance:</p> <p>The road surface is maintained. No pot holes found. The riding is smooth.</p>				
b	Observations: What is the pavement condition index (PCI) as per annexure 14.7 para 14.9 of Operations manual?	5	4 ✓	3	< 3
c	Grading for the above item	S / U 'S'			
4	Name of Item/ Activity : Maintenance of drains as per clause 1907 of the Specifications, Maintenance of culverts and cause ways as per clause 1908 and 1909 of the Specifications				
a	<p>Observations: What is the condition of Roads in respect to this item :</p> <p>No provision of drains in DBR. Culverts are well maintained</p>				
b	Grading for the above item	✓ S / U 'S'			

5	Name of Item/ Activity : Maintenance of road signs as per clause 1910 of the Specifications and White washing guard stones, Re-fixing displaced guard stones, White washing parapets of C.D. Works	
a	Observations: What is the condition of Roads in respect to this item : The logo board, Citizen information board, maintenance board and Parapets of Culverts Painted	
b	Grading for the above item	✓ S/U 'S'
6	Name of Item/ Activity: Maintenance of guard rails and parapet rails as per clause 1911 of the Specifications, Maintenance of 200 m and Kilo Meter stones as per clause 1912 of the Specifications.	
a	Observations: What is the condition of Roads in respect to this item : No provision of guard rails. Parapets maintained. KM. Stone maintained. 200m posts not found.	
b	Grading for the above item	S/U ✓ 'U'
7	Over all grading	S/ SRI/ U SRI


13/12/18
Signature

Date: 13-12-2018

Name of SQM/PIU ✓
Executive Engineer
R.W.D. Works Division
Jamul

Name of road : Sahia Main road – Chandrapura.

Package No. : BR-15R-103

Date of Inspection : 13.12.2018



Main Information board, Logo board, Citizen board and Maintenance board



General view of road and HP Culvert

Name of road : Sahia Main road – Chandrapura.

Package No. : BR-15R-103

Date of Inspection : 13.12.2018



Patch repair