
Format for Inspection of Maintenance Aspects of completed PMGSY/MMGSY works

1.	Date of Inspection: - 1- 13.12.18
2.	Name of National Quality Monitor: Yugeshwas Kumas Singh
3.	State: Bihare District: supaul Block: Piprea
4.	Name of Road: From Ram Nagar to Yadav Tola
5.	Package No.: BR-35R-084
6.	Year of clearance: 00-01 Ph-1 01-03 Ph-2 03-04Ph-3 04-05 Ph-4 05-06 Ph-5
7.	Length: Flexible PavementKm CC/other PavementKm. = Total 3:325 Km.
8.	Estimated Cost (As cleared by GOI): Rs. 253.20 Lakh
9.	Cost upon Completion: Rs. 218.36 Lakh
10.	The Work is a Case of: New connectivity Up gradation
11.	Actual Date of Completion: 14 07 2016
Ob	Actual Date of Completion: 14 07 2016 Servations: FEXECUTIVE Engineer RWD (W) Divn. Triveniganj
1	Name of Item/ Activity: Maintenance of road in respect to Restoration of rain cuts as per clause 1902 of the Specifications and Cutting of branches of trees, shrubs and trimming of grass and weeds etc as per clause 1914 of the Specifications.
a	Observations: What is the condition of Roads in respect to this item: The
	condition of the Road with respect to C1. 1902 is good
	Trimming of grass and weeds have been done in
	large partien and the remaining work is going.
	on with full effort
b	Grading for the above item SYU
2	Name of Item/ Activity: Restoration of rain cuts and dressing of berms as per clause 1902 of the Specifications and making up of shoulders as per clause 1903 of the Specifications
a	Observations: What is the condition of Roads in respect to this item: Raus cuts
	and dressing of burn is going on properly
-	



b	Crading for the al.	/		717	
	- Charles and Charles	SI			
3	Condition of Pavement including filling pot holes per clause 1904, 1905 and 1906 of the Specification	and j	oatch 1	epair	s etc as
a	Observations: What is the condition of Roads in recobservations should be made as to whether the paven reveling etc which is causing disturbance/discomfort these defects have been repaired properly under routin NO Pot holes, cracking, ravelling or Mafe cracking was found in earlies abrasion in C.C. Powement in a Maintenance have been done	nent ha in driv	s pothering?	oles, co	racking,
b	Observations: What is the pavement condition index	5	11	2	1 - 2
	(PCI) as per annexure 14.7 para 14.9 of Operations manual?	3	130	3	< 3
c	Grading for the above item	S/U			
4	Name of Item/ Activity: Maintenance of drains a Specifications, Maintenance of culverts and cause was 1909 of the Specifications	is per lys as j	per clai	ise 19	of the 08 and
1	Observations: What is the condition of Roads in respec	t to thi	s item	:	
	Three culvert have been trepai	nted	one	cul	vert
	emaine to be bainted But Tou	nte	e we	2	
	madalal at the of it. There	cul	vert.	, and	el
	ready to get discharge it me	ans	4h	ege	ere
	clean .				
-					4 3

		S/U			
Gr	ading for the above item	as per clause 1910 of the			
Na Sp	Name of Item/ Activity: Maintenance of road signs to personal specifications and White washing guard stones, Re-fixing displaced guard specifications and White washing guard stones, Re-fixing displaced guard specifications and White washing guard stones.				
sto	bservations: What is the condition of Roads in resp	ect to this item:			
7	bservations: What is the condition of Roads in respondente nance of road signis In Maintenance Board, Maintenance Board, Maintenance Board displane: More than 90 010 displanteness have been fixed books stones have been fixed books.	god have been laced guas al			
		CIT			
	Grading for the above item	S/U			
5	Grading for the above item Name of Item/ Activity: Maintenance of guard clause 1911 of the Specifications, Maintenance of as per clause 1912 of the Specifications.	rails and parapet rails as per 200 m and Kilo Meter stones			
5	Name of Item/ Activity: Maintenance of guard clause 1911 of the Specifications, Maintenance of as per clause 1912 of the Specifications. Observations: What is the condition of Roads in read the specification of Roads in read to small state the s	rails and parapet rails as per 200 m and Kilo Meter stones			
5	Name of Item/ Activity: Maintenance of guard clause 1911 of the Specifications, Maintenance of as per clause 1912 of the Specifications. Observations: What is the condition of Roads in read 200 M (Hectometrs stone) Kilometr stone have been	rails and parapet rails as per 200 m and Kilo Meter stones espect to this item: Mainter was going on But main Tained			
5	Name of Item/ Activity: Maintenance of guard clause 1911 of the Specifications, Maintenance of as per clause 1912 of the Specifications. Observations: What is the condition of Roads in read 200 M (Hectometrs stone) Kilo multir stone have been	rails and parapet rails as per 200 m and Kilo Meter stones			

Signature
| 3|12|18|
| Executive Enginner
| R.W.D. Work |
| Division, Supaul.

Date: 13/12/19