

UP-15-110364(110)/CIVIL(110)-23-155/2017-3084 4291/1103-18/02/19

Annexure-5

Format for Inspection of Maintenance Aspects of completed Work

1. Date of Inspection: 23.7.2019
2. Name of Principal Quality Monitor: PARTHA PRATIM GHOSH
3. State: Bihar District: MUZAFFARPUR Block: MOTIPUR
4. Name of Road: From MANPUR TO MAINPUR MAI STHAN  
DHABI TOLA POKHAR.
5. Package No: MMGSY ROAD.
6. Year of Clearance:
7. Length in Flexible pavement- CC/other pavement- Km. Total-1.550 km
8. Estimated Cost (As cleared by GOI): ₹ 123.56836 Lakh.
9. Cost upon Completion: ₹ 111.21152 Lakh
10. The Work is a Case of: New connectivity / Up-gradation
11. Actual Date of Completion: 12.5.2016

**Observations:**

1	<b>Name of Item/ Activity:</b> Maintenance of road in respect to Restoration of rain cuts as per clause 1902 of the Specifications and Cutting of branches of trees shrubs and trimming of grass and weeds etc as per clause 1914 of the Specifications. RAIN CUTS have developed at several Places.
A	<b>Observations:</b> What is the condition of Roads in the respect of this item? Not good.
B	<b>Grading for the above item</b> Unsatisfactory 'U'
2	<b>Name of Item/ Activity:</b> Restoration of rain cuts and dressing of beams as per clause 1902 of the specifications and making up of shoulders as per Clause (507) of the Specifications. Grass, shrubs, weeds have grown on flank, shoulder. Mud has deposited on both the sides of road reducing the carriage way.
A	<b>Observations:</b> What is the condition of Roads in the respect of this item Unsatisfactory 'U'
B	<b>Grading for the above item</b> Unsatisfactory U
3	<b>Condition of Pavement including filling pot holes and patch repairs etc as per clause 1904, 1905 and 1906 of the Specifications.</b> PMC has worn out at few places.



A	<b>Observations:</b> What is the condition of Road in respect to this item (Detailed) observations should be made as to whether the pavement has pot holes. Cracking revealing etc which is causing disturbance/ discomfort in driving? If yes, these defects been remained properly routing maintenance <i>PMC. has worn out at few places</i>				
B	<b>Observations:</b> What is the pavement condition index (PCI) as per annexure 14.7 Para 14.9 of Operations manual?	5	4	3	<3
C	<b>Grading of the above item</b> <i>SRI</i>			✓	
4	<b>Name of Item/ Activity:</b> Maintenance of drains as per clause 1907 of the Specification, Maintenance of culverts and cause ways as per clause 1908 and 1909 of the Specifications <i>Well maintained Culvert.</i>				
A	<b>Observations:</b> What is the condition of Roads in the respect of this item? <i>Good</i>				
B	<b>Grading of the above item</b> <i>S</i>	S/U			
5	<b>Name of Item/ Activity:</b> Maintenance of Road signs as per clause 1910 of the Specification are white washing guard stones Re-fixing displaced Guard stones, white washing parapet's of C.D. works <i>Road Signages, Information Board, should be restored</i>				
A	<b>Observation:</b> What is the condition of Roads in the respect of this item. <i>Unsatisfactory</i>				
B	<b>Grading of the above item</b> <i>U</i>	S/U			
6	<b>Name of Item/ Activity:</b> Maintenance of guard rails and parapet rails as per clause 1911 of the Specifications, maintenance of 200 m and Kilo Meter stones as per clause 1912 of the Specifications. <i>200m stones, Kilo Meter stones should be restored, repainted</i>				
A	<b>Observation :</b> What is the condition of Roads in the respect of this item <i>Unsatisfactory</i>				
B	<b>Grading for the above item</b> <i>U</i>	S/U			
7	<b>Over all grading</b> <i>SRI</i>	S/U			

Date: 23.7.2019 .

Partha Pratim Ghosh  
Signature  
INSPECTING OFFICER